



Mercedes-Benz CLA 200: K787SB

Vinnumber:	W1K1186121N199340	Versionname:	CLA200d 2.0 110kW Business Luxury Shooting Brake DCT
First Registrationdate:	11/03/2021	Fiscalpower:	
Expertise Mileage:	68995	Power Kw:	110
Bodytype:		Body colour:	Kosmoszwart metallic
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Back	Type of rims (mounted):	Aluminium
Fueltype:	Diesel	Parking lot:	1011
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
Number keys remote	2	Lining leather
GPS		Sun Roof electric
GPS storage		Panoramic roof
GPS storage	HD	Central consol F
Autom climate control		Luggage cover
Windows electric F		Headlights Xenon/LED/Laser
Radio multimedia		Front parking sensors
		Rear parking sensors

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 55 / 17 / 95 / V / Aluminium	5,0 mm	Goodyear	Summer
	Right	205 / 55 / 17 / 95 / V / Aluminium	4,0 mm	Goodyear	Summer
Rear	Left	205 / 55 / 17 / 95 / V / Aluminium	6,0 mm	Bridgestone	Summer
	Right	205 / 55 / 17 / 95 / V / Aluminium	4,0 mm	Bridgestone	Summer

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Door RL, Scratch(es), Repair and paint (complete)



Roof pillar L, Dent(s), Paintless dent repair



Door FL, Scratch(es), Repair and paint (complete)



Brand badge F, Broken, Replace



Bumper moulding F, Broken, Replace



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Bonnet, Chemical polution, Polish



Door FR, Dent(s), Repair and paint (complete)



Wing FR, Scratch(es), Polish




Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Roof pillar R, Dent(s) and scratch(es), Repair and paint (complete)



Rear spoiler, Chemical polution, Polish



Bumper R, Scratch(es), Repair and paint (complete)



Roof, Chemical polution, Polish

