



MERCEDES-BENZ CLA
CLA 250 Shooting Brake 7G-DCT

VIN NO W1K1186461N247001
Registration Number 461N247001



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-07-01	1	2	39754 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2024-07-29	28706	2021-07-22	Germany

Inspection Report Summary


Customer	BCA Online	Report Number	P20250923095912
Inspection Date / Place	2025-09-23 / ARS Altmann AG Riedstadt	Cosmetic Grade	3

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Petrol	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1991
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth/Synthetic Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Computer Print Out Available	Next Service Mileage	km
Previous Usage	Imported	No	
Manufacturer Warrenty			







Equipment

Trip Computer	Airbag Status	Anti-lock braking	Cruise control
Digitaldashboard	Remote adjusting wing mirrors	Reversing Camera	Stability control
Electrically folding wing mirrors	Leather steering wheel	Radio	USB Socket
Alloys wheels	Bluetooth telephone interface	Digital Radio	Front parking sensors
Remote central locking	Satellite navigation	Electrically adjustable seats	Electrictailgate
LED Headlamps	Rear parking sensors		

Equipment Details


Air Conditioning	Climate Control	Alloy Wheel Size	18
Seat Heating	Front		

Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

Cosmetic Damage


7 Schäden



0 Schäden




Component	Damage	Comments
1 Hood	Bodywork / Dent / Dent	
2 Bumper / Front	Paint / Scratch / Scuff	
3 Rear Window / Back	Glass Break / Scratch / Scratch	
4 Tailgate	Paint / Poor Previous Repair	
5 Door / Back Left	Paint / Poor Previous Repair	
6 Door / Front Left	Paint / Poor Previous Repair	
7 Door / Front Right	Paint / Poor Previous Repair	



1. Hood
Bodywork / Dent / Dent -



2. Bumper / Front
Paint / Scratch / Scuff -



3. Rear Window / Back
Glass Break / Scratch / Scratch -



4. Tailgate
Paint / Poor Previous Repair -



5. Door / Back Left
Paint / Poor Previous Repair -



7. Door / Front Right
Paint / Poor Previous Repair -

Mechanical Condition

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	!
Tire Pressure Monitoring System	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Audio Equipment	✓	AC / Heating System	✓
Other Equipments	✓	Central Locking	✓
Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Parking Sensors / Cameras Functioning	✓

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)