


Vehicle details

VIN	W1K118687 1N187865	Brand	MERCEDES-BENZ	Maintenance date	-
Licence Plate	K9-84-FV	Model	CLA Shooting Brake CLA 200 DCT Business Solution A	Maintenance mileage	-
Registration date	10/12/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	127 176 km	Engine size	1332	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details


Inspection date	05/06/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Sliding roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element




Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 225/45/18 Summer 6.5 mm



Pirelli 225/45/18 Summer 6.5 mm



Pirelli 225/45/18 Summer 6.5 mm

Pirelli 225/45/18 Summer 6.5 mm

Exterior

1



Part

Alloy wheel 18"

Position

Front left

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

2



Part

Step plate

Position

Front left

Damages

Scratched

Severity

-

Repair mode

For info

3



Part

Bumper moulding

Position

Back left

Damages

Broken

Severity

-

Repair mode

Replace

4



Part

Tailgate / Boot door

Position

-

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

5



Part

Alloy wheel 18"

Position

Back right

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

6



Part

Door

Position

Front right

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

7



Part

Alloy wheel 18"

Position

Front right

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

8



Part

Spoiler

Position

Front right

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

9



Part

Spoiler

Position

Front left

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

10



Part

Spoiler

Position

Front

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair