



**MERCEDES A: 1YAC123**

Vinnumber:	<b>W1K1770031N169734</b>	Versionname:	<b>A 180 d Business Solution</b>
First Registrationdate:	<b>26/06/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>51935</b>	Power Kw:	<b>85</b>
Bodytype:		Body colour:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>3313</b>
Fueltype:	<b>Diesel</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

**Options**

Number of keys total:	<b>2</b>	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	<b>Tow bar collapsible</b>
Radio multimedia:			
Type of headlighting:	<b>Headlighting LED</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining semi-artificial leather</b>		
Type of climate control:	<b>Autom climate control</b>		

**Limited Technical Inspection**

**Tyres**

<b>205/60/16/92 V</b>				
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 2 mm</b>
	Re.L.	<b>Kumho: 2 mm</b>	Re.R.	<b>Kumho: 2 mm</b>
Tyre profile depth FL				<b>4.0</b>
Tyre profile depth FR				<b>2.0</b>
Tyre profile depth RL				<b>2.0</b>
Tyre profile depth RR				<b>2.0</b>
Tyre size FL				<b>205/60 R 16 92 V</b>
Tyre size FR				<b>205/60 R 16 92 V</b>
Tyre size RL				<b>205/60 R 16 92 V</b>
Tyre size RR				<b>205/60 R 16 92 V</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>256</b>
Tyre make FR				<b>256</b>
Tyre make RL				<b>2482</b>
Tyre make RR				<b>2482</b>


**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

<b>Total cost ex VAT</b>	<b>433,28</b>
<b>Interior, Damaged, Acceptable</b>	<b>0,00</b>



Bonnet, Scratch(es), Polish 0,00



Windscreen moulding, Scratch(es), Acceptable 0,00



Door FL, Scratch(es), Acceptable 0,00



Wing RL, Dent(s), Acceptable 0,00



Rear window, Scratch(es), Replace 433,28



Rear spoiler, Scratch(es), Polish 0,00



Alloy rim FR polished, Rust, Acceptable 0,00



Door RR, Scratch(es), Acceptable 0,00



Roof, Scratch(es), Polish 0,00

