

# INSPECTION REPORT

**End Of Contract**

## GENERAL INFO

|                               |                           |
|-------------------------------|---------------------------|
| File                          | 288538                    |
| License plate                 | 1XXD794                   |
| Vehicle identification number | W1K1770031N173461         |
| Dossier                       | 2020 037 200              |
| Make                          | Mercedes A 180 d Bus Sol. |
| Mileage                       | 99507.00                  |
| First registration            | 22/06/2020                |
|                               | 08/07/2025                |

## CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | Y       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | N       |        |
| Towbar (+keys)            |        | N       |        |
| Certificate of conformity |        | Y       |        |
| Registration certificate  |        | Y       |        |
| Repair kit                |        | Y       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | N       |        |
| Charge back wrong tyres   |        | N       |        |





## DAMAGES

| Damages | Type                                 | Acceptable |
|---------|--------------------------------------|------------|
| 95      | Rocker Panel Left // Polish          | Y          |
| 152     | Rear Bonnet // Smart Repair Large    | N          |
| 159     | Rear Bonnet / Rear Window / Replace  | N          |
| 216     | Door Front Right // Polish           | Y          |
| 569     | Dashboard / Steering Wheel / Replace | Y          |
| 860     | Interior Cleaning // Small           | N          |


## Damage Pictures



Door Front Right // Polish-scratch



Rear Bonnet // Smart Repair Large-scratch



Rear Bonnet / Rear Window / Replace-scratch



Rocker Panel Left // Polish-scratch



Interior Cleaning // Small-stain



Dashboard / Steering Wheel / Replace-worn