

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	288600
License plate	RP7284
Vehicle identification number	W1K1770031N180844
Dossier	2021 172 026
Make	Mercedes A 180 136 Aut
Mileage	118066
First registration	08/07/2021
client availability date	09/07/2025
inspectionDate	11/07/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
54	Headlight / Front left / Replace	N
61	Wing Front Left // Smart Repair Medium	N
274	Bumper Front / Grid Central / Replace	N
84	Door Front Left // Repair & Painting	N
91	Rocker Panel Left // Smart Repair Medium	N
136	Bumper Rear // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
165	Roof // Polish	Y
196	Door Rear Right // Polish	Y
320	Wheel Two Tone Rear Left // Repair	Y

Damage Pictures




Door Rear Right // Polish-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear // Polish-scratch



Roof // Polish-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Wheel Two Tone Rear Left // Repair-Chemical reaction



Bumper Front / Grid Central / Replace-bad position



Wing Front Left // Smart Repair Medium-scratch



Headlight / Front left / Replace-scratch



Bumper Front // Painting-scratch