


MERCEDES A: 1Y639

Vinnumber:	W1K1770821V077277	Versionname:	A 160 Business Solution
First Registrationdate:	10/08/2020	Fiscalpower:	
Expertise Mileage:	94585	Power Kw:	80
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1722
Fueltype:	Petrol		
Maintenance:	OK		
Maintenance:	over 339 dagen		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting Halogen		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining semi-artificial leather		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection
Tyres

205/60/16/96 W				
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/60 R 16 96 W
Tyre size FR				205/60 R 16 96 W
Tyre size RL				205/60 R 16 96 W
Tyre size RR				205/60 R 16 96 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit:	Yes	Compressor:	No
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	28,43
Windscreen, Stone chip(s), Acceptable	0,00



Bonnet, Stone chip(s), Acceptable 0,00



Bumper F, Scratch(es), Acceptable 0,00



Outside rear-view mirror housing L, Scratch(es), Acceptable 0,00



Door FL, Scratch(es), Acceptable 0,00




Wing RL, Scratch(es), Acceptable 0,00



Alloy rim FL polished, Chemical polution, Acceptable 0,00



Alloy rim RL polished, Chemical polution, Acceptable 0,00



Tyre repair kit, Missing, Replace 0,00



Boot carpet, Dirty, Cleaning

28,43



Boot lid covering R, Scratch(es), Acceptable

0,00



Tailgate / Boot, Dent(s), Acceptable

0,00



Step R, Scratch(es), Acceptable

0,00



Wing RR, Dent(s), Repair and paint (complete)

0,00



Door RR, Scratch(es), Acceptable

0,00



Alloy rim RR polished, Chemical polution, Acceptable

0,00



Alloy rim FR polished, Chemical polution, Acceptable

0,00

