



MERCEDES A: 1YLF317				
Vinnumber:	W1K1770861J267287	Versionname:	A 250 e Business Solution	
First Registrationdate:	28/09/2020	Fiscalpower:		
Expertise Mileage:	48644	Power Kw:	160	
Bodytype:		Body colour	Black	
Gearbox:	Automatic	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	3712	
Fueltype:	Hybrid Petrol			
Maintenance	OK			
Maintenance	Service A +34 d			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Luggage cover		
Cruise Control		Front parking sensors		
Steering wheel multifunctional		Rear parking sensors		
Seats F heated		Type of Tow bar	No Tow bar	
Radio multimedia				
Type of headlighting	Headlighting LED			
Type of GPS	GPS big screen color			
Type of Lining	Lining semi-leather			
Type of climate control	Autom climate control			
Adaptive cruise control				
Type of GPS storage	HD			
Limited Technical Inspection				
Tyres				
Summer tyres:	225/45/18/91 W			
	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				225/45 R 18 91 W
Tyre size FR				225/45 R 18 91 W
Tyre size RL				225/45 R 18 91 W
Tyre size RR				225/45 R 18 91 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264
Assistance equipment				
Repair kit	Yes	Compressor		Yes
Number of charging cables (normal)	1			
Number of charging cables (rapid charge)	1			
Total cost ex VAT				436,68
Bonnet, Stone chip(s), Acceptable				0,00



Bumper F, Scratch(es), Spot repair	144,58
------------------------------------	--------



Wing RL, Dent(s), Paintless dent repair	93,06
---	-------



Alloy rim RL polished, Rust, Repair and paint (complete)	199,04
--	--------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Outer door handle FR, Scratch(es), Acceptable	0,00
---	------



Alloy rim FR polished, Scratch(es), Acceptable	0,00
--	------



Fuel cap cover, Chemical pollution, Acceptable	0,00
--	------

