

Inspection Protocol



MERCEDES BENZ A 250 E 8G-DCT, 218HK, 2021

Vehicle information

License plate	YYE71P	Inspected by	A.H.
Year model	2021	Date of inspection	2025-03-13
Manuf. year/month	2020-12	City	Falkenberg
First day in traffic	2021-01	Keys	2
Colour	Svart	Service book	Elektronisk servicebok
Mileage	123 460 km	Latest service	-
Fuel	Elhybrid	Mileage at the latest service -	
Transmission	Automat	Summer tires	18" alu-fälg 3/3/6/6
Engine effect	160 kW	Winter tires	alu-fälg dubbat 5/6/6/5

Damages

Location	Damage	Comments	Costs excluding VAT
Rims & Tires, Summer	Rim damage 4 wheel		440 €
Wing, Front left	Scratches below 30 mm		60 €
Tak, A-pillar	Stenskott/ repa	Vänstersidan	0 €
Door, Front left	Scratches below 30 mm		60 €
Door, Rear left	Paint retouch traces		0 €
Bumper, Rear	Cargo scratches		150 €
Door, Rear right	Scratches below 30 mm		60 €
Wing, Front right	Paint retouch traces		0 €
Bumper, Front	Scratches below 30 mm	Samt stenskott	60 €
Bonnet	Chip		60 €
Glass, Windshield	Cracks small (max 30 mm)		220 €
Tak, Tak	Chip		60 €
Rims & Tires, Winter	Rim damage 1 wheel	HB skada	110 €
Service	Due now		360 €
Other, Other	Other	Komplett bilmapp saknas	-

Total excl. VAT	1 640 €
-----------------	---------

Service occasions

1500-MIL, 4000-MIL, 6500-MIL, 10000-MIL

Images

[See all images in large format](#)
























Fälgar & Däck Sommar Fälgskada 4 hjul 6 000 kr



Skärm Vänster fram Repor under 3 cm 800 kr



Tak A-stolpe Stenskott/ repa Vänstersidan 50 kr



Dörr Vänster fram Repor under 3 cm 800 kr



Dörr Vänster bak Lackbättring 50 kr



Stötfångare Bak Lastrepor 2 000 kr



Dörr Höger bak Repor under 3 cm 800 kr



Skärm Höger fram Lackbättring 50 kr




Stötfångare Fram Repor under 3 cm Samt stenskott 800 kr




Motorhuv Stenskott 800 kr



Glas Vindruta Sprickor små (max 3 cm) 3 000 kr



Tak Tak Stenskott 800 kr







Fälgar & Däck Vinter Fälgskada 1 hjul HB skada 1 500 kr