



Mercedes A-Klasse (UKL): 2ATR598

Vinnumber:	W1K1770871N249758	Versionname:	A200 1.3i 163pk/cv 5p
First Registrationdate:	13/07/2021	Fiscalpower:	
Expertise Mileage:	87544	Power Kw:	120
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	+ 13 dagen		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
Type of Maintenance book	Digital maintenance	Type of Tow bar	No Tow bar
Type of GPS storage	N.A.		

Tyres

	205/55/17/91 W			
Summer tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 17 91 W
Tyre size FR				205/55 R 17 91 W
Tyre size RL				205/55 R 17 91 W
Tyre size RR				205/55 R 17 91 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Steering wheel, Worn, Acceptable



Backrest cover RL, Scratch(es), Acceptable



Bonnet, Scratch(es), Acceptable



Bumper F, Broken, Replace and paint



Alloy rim RL polished, Rust, Acceptable



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Sill trim L, Scratch(es), Repair and paint (complete)





Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Mirror side repeater L, Scratch(es), Replace



Outside rear-view mirror base L, Scratch(es), Smart repair



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Boot lid covering R, Scratch(es), Acceptable



Rear bulkhead lining, Scratch(es), Acceptable



Tailgate / Boot, Dent(s), Paintless dent repair



Bumper R, Scratch(es), Repair and paint (complete)



Rear light L, Scratch(es), Replace



Outside rear-view mirror housing R, Scratch(es), Polish



Mirror side repeater R, Scratch(es), Replace



Outside rear-view mirror base R, Scratch(es), Smart repair



Sill trim R, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Spot repair

