

INSPECTION REPORT


End Of Contract

GENERAL INFO

File	282282
License plate	1YFN253
Vehicle identification number	W1K1771031J255552
Dossier	2020 042 114
Make	Mercedes A Berline 180 d Busin
Mileage	190576.00
First registration	14/08/2020
	05/06/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
860	Interior Cleaning // Small	N

Damage Pictures



Interior Cleaning // Small-stain



Bumper Front // Repair & Painting-bad position