


**MERCEDES A BERLINE: 1YPB983**

Vinnumber:	<b>W1K1771031J269597</b>	Versionname:	<b>A 180d Business Solution</b>
First Registrationdate:	<b>16/10/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>63164</b>	Power Kw:	<b>85</b>
Bodytype:		Parking lot	<b>1533</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted)	<b>Aluminium</b>
Transmission:		Body colour	<b>Black</b>
Fueltype:	<b>Diesel</b>		
Certificate of Conformity	<b>Yes</b>		
Type of rims (mounted)	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Registration Certificate Home (BE)	<b>No</b>		
Registration Certificate Car (BE)	<b>Yes</b>		
Maintenance	<b>OK</b>		
Maintenance	<b>A in 17 days</b>		

**Options**

Radio multimedia		Rear parking sensors	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Type of Tow bar	<b>No Tow bar</b>
Type of GPS storage	<b>HD</b>		
Type of GPS	<b>GPS big screen color</b>		
Cruise Control			
Type of climate control	<b>Autom climate control</b>		
Number of keys total	<b>2</b>		
Type of headlighting	<b>Headlighting Halogen</b>		
Type of Lining	<b>Lining fabrics</b>		

**Limited Technical Inspection**
**Tyres**

Tyre size RL	<b>205/60 R 16 92 V</b>
Tyre type FL	<b>Summer</b>
Tyre type RL	<b>Summer</b>
Tyre profile depth FR	<b>4.0</b>
Tyre profile depth RR	<b>5.0</b>
Tyre make FR	<b>256</b>
Tyre size FR	<b>205/60 R 16 92 V</b>
Tyre make RR	<b>256</b>
Tyre size RR	<b>205/60 R 16 92 V</b>

**205/60/16/92 V**

Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

Tyre profile depth FL	<b>4.0</b>
Tyre make FL	<b>256</b>
Tyre size FL	<b>205/60 R 16 92 V</b>
Tyre type FR	<b>Summer</b>
Tyre profile depth RL	<b>5.0</b>
Tyre type RR	<b>Summer</b>
Tyre make RL	<b>256</b>

**Assistance equipment**

Number of charging cables (normal)	<b>0</b>	Compressor	<b>Yes</b>
Number of charging cables (rapid charge)	<b>0</b>		
Repair kit	<b>Yes</b>		

Total cost ex VAT	<b>347,07</b>
Bumper F, Dent(s) and scratch(es), Repair and paint (complete)	<b>347,07</b>



Windscreen, Repaired, Acceptable 0,00



Door RL, Dent(s) and scratch(es), Acceptable 0,00



Wing RL, Scratch(es), Acceptable 0,00



Alloy rim RL polished, Rust, Acceptable 0,00



Wing RR, Scratch(es), Acceptable 0,00



Door RR, Scratch(es), Acceptable 0,00



Bodywork, Not original part, Remove lettering 0,00

