

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	293887
License plate	LP1703
Vehicle identification number	W1K1771861J314931
Dossier	2021 124 001
Make	Mercedes A Sedan 250e 160 Aut
Mileage	89691
First registration	19/05/2021
client availability date	10/09/2025
inspectionDate	12/09/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
194	Door Rear Right // Repair & Painting	N
202	Rocker Panel Right // Painting	N
13	Bumper Front // Painting	N
41	Windshield // Replace	N
84	Door Front Left // Repair & Painting	Y
104	Door Rear Left // Repair & Painting	Y
114	Wing Rear Left // Repair & Painting	N
135	Bumper Rear // Replace & Painting	N
184	Wing Rear Right // Repair & Painting	Y
213	Door Front Right // Painting	N
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N

Damage Pictures





Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Front // Painting-scratch



Windshield // Replace-scratch



Door Front Right // Painting-scratch




Wing Rear Right // Repair & Painting-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent




Door Front Left // Repair & Painting-scratch + dent



Bumper Rear // Replace & Painting-cracked



Rocker Panel Right // Painting-scratch



Door Rear Right // Repair & Painting-scratch + dent