



Mercedes C-Klasse (KKL): 1YED127

Vinnumber:	W1K2050001R592996	Versionname:	C180d Sedan Business Solution 1.6d 122pk/cv 4p
First Registrationdate:	3/08/2020	Fiscalpower:	
Expertise Mileage:	111864	Power Kw:	90
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	Service B +262 d		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Type of Tow bar	Tow bar removable
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/60/16/96 H			
Winter tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/60 R 16 96 H
Tyre size FR				205/60 R 16 96 H
Tyre size RL				205/60 R 16 96 H
Tyre size RR				205/60 R 16 96 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Interior, Damaged, Acceptable




Ignition key, Missing, Replace



Instrument panel, complete, Not functioning (well), Check




Interior, Stain, Cleaning



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FL, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Wing RL, Dent(s) and scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Bumper trim R, Scratch(es), Acceptable



Wing RR, Dent(s), Paintless dent repair



Door FR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Acceptable

