



MERCEDES C BREAK: 1YBJ871				
Vinnumber:	W1K2052001G025876	Versionname:	C 180 d Business Solution	
First Registrationdate:	7/07/2020	Fiscalpower:		
Expertise Mileage:	177427	Power Kw:	90	
Bodytype:		Body colour	Dark Grey	
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	2716	
Fueltype:	Diesel			
Maintenance	OK			
Maintenance	A in 4900 km			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Seats electric F L		
Cruise Control		Seats electric F R		
Steering wheel multifunctional		Luggage cover		
Seats F heated		Front parking sensors		
Radio multimedia		Rear parking sensors		
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar	
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Autom climate control			
Type of GPS storage	SD present			
Limited Technical Inspection				
Tyres				
	205/60/16/96 V			
Summer tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				205/60 R 16 96 V
Tyre size FR				205/60 R 16 96 V
Tyre size RL				205/60 R 16 96 V
Tyre size RR				205/60 R 16 96 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				265
Tyre make FR				265
Tyre make RL				265
Tyre make RR				265
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT			144,58	
Steering wheel, Worn, Acceptable			0,00	



Seat cover FL, Stain, Acceptable	0,00
----------------------------------	------



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------



Tailgate / Boot, Scratch(es), Spot repair	144,58
---	--------



Alloy rim FR, Scratch(es), Acceptable	0,00
---------------------------------------	------

