



MERCEDES C BREAK: 1YCA812				
Vinnumber:	W1K2052001G036805	Versionname:	C 180 d Business Solution	
First Registrationdate:	13/07/2020	Fiscalpower:		
Expertise Mileage:	119452	Power Kw:	90	
Bodytype:		Body colour	Dark Grey	
Gearbox:	Automatic	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	3808	
Fueltype:	Diesel			
Maintenance	OK			
Maintenance	B7 over 230 dagen			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Luggage cover		
Cruise Control		Front parking sensors		
Steering wheel multifunctional		Rear parking sensors		
Seats F heated		Type of Tow bar	Tow bar collapsible	
Radio multimedia				
Type of headlighting	Headlighting LED			
Type of GPS	GPS big screen color			
Type of Lining	Lining leather			
Type of climate control	Autom climate control			
Type of GPS storage	SD present			
Limited Technical Inspection				
Tyres				
Summer tyres:	205/60/16/92 V			
	Fr.L.	Kumho: 5 mm	Fr.R.	Kumho: 5 mm
	Re.L.	Kumho: 4 mm	Re.R.	Kumho: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				4.0
Tyre profile depth RR				6.0
Tyre size FL				205/60 R 16 92 V
Tyre size FR				205/60 R 16 92 V
Tyre size RL				205/60 R 16 92 V
Tyre size RR				205/60 R 16 92 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2482
Tyre make FR				2482
Tyre make RL				2482
Tyre make RR				2482
Assistance equipment				
Repair kit	Yes	Compressor		Yes
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT				438,74
Floor covering FL, Worn, Acceptable				0,00



Interior covering A pillar R, Hole, Forfeit

5,00



Bumper F, Scratch(es), Spot repair

144,58



Alloy rim FL, Scratch(es), Acceptable

0,00



Boot lid covering R, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Spot repair

144,58




Wing RR, Dent(s), Spot repair

144,58



Outer door handle FR, Scratch(es), Acceptable

0,00



Wing FR, Dent(s) and scratch(es), Acceptable

0,00



Bodywork, Not original part, Remove lettering

0,00

