



MERCEDES C BREAK: 1YNQ529			
Vinnnumber:	W1K2052531G050840	Versionname:	C 300 e Business Solution Auto
First Registrationdate:	13/10/2020	Fiscalpower:	
Expertise Mileage:	151389	Power Kw:	235
Bodytype:		Body colour	Blue
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2821
Fueltype:	Hybrid Petrol		
Maintenance	NOT OK		
Maintenance	service B5 sinds 900km		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options			
Number of keys total	1	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar collapsible
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		
Adaptive cruise control			
Type of GPS storage	HD		

Limited Technical Inspection

Degree of wear

225/45/18/95 Y				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 2 mm	Re.R.	Goodyear: 2 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				2.0
Tyre profile depth RR				2.0
Tyre size FL				225/45 R 18 95 Y
Tyre size FR				225/45 R 18 95 Y
Tyre size RL				245/40 R 18 97 Y
Tyre size RR				245/40 R 18 97 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Number of charging cables (normal)	2
Number of charging cables (rapid charge)	1

Total cost ex VAT	3606,79
Service, Maintenance, Check	0,00



Ignition key, Missing, Replace

341,22



Seat cover FL, Worn, Check

0,00



Bonnet, Dent(s), Acceptable

0,00



Bumper F, Scratch(es), Repair and paint (complete)

289,07



Alloy rim FL polished, Scratch(es), Repair and paint (complete)

199,04



Alloy rim RL polished, Scratch(es), Repair and paint (complete)

199,04





Door FL, Scratch(es), Acceptable

0,00



Wing RL, Dent(s) and scratch(es), Acceptable

0,00



Luggage compartment cover, Missing, Replace

801,72



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)

318,07



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)

449,65





Door RR, Scratch(es), Repair and paint (complete)

434,50



Alloy rim RR polished, Scratch(es), Repair and paint (complete)

199,04



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

199,04



Tyre FR, Tear, Replace

176,40

