



MERCEDES-BENZ E-Klasse  
AMG E 63 S 4Matic+ T AMG Speedshift  
MCT-9G

VIN NO W1K2132891B053892  
Registration Number 891B053892



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2027-06-01	1	2	98904 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2024-12-12	-	2022-03-09	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250917151124
Inspection Date / Place	2025-09-17 / ARS Altmann AG Riedstadt	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Petrol	Road Worthy	Yes
Colour	White	Engine Size (cc)	3982
Engine Size	4.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			











## Equipment

Tinted Glass	Traffic sign recognition	USB Socket	Adaptive cruise control
Alloys wheels	Anti-lock braking	Cruise control	Digital dashboard
Front parking sensors	Heated wing mirrors	Remote adjusting wing mirrors	Roof rails
Seat ventilation	Stability control	Central locking	Electrically adjustable seats
Electric tailgate	Lane assist	LED Headlamps	Rain sensitive windscreen wipers
Tow ball	Trip Computer	360° camera	Airbag Status
Ambient lighting	Bluetooth telephone interface	Digital Radio	Enhanced speaker system
Head up Display	Parking Assistance	Remote central locking	Satellite navigation
Split folding rear seats	Sunroof	Distance warning system	Electrically folding wing mirrors
Emergency brake assist	Leather steering wheel	Radio	Rear parking sensors

## Equipment Details


Tow Ball Type	Electronic	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	20	Seat Heating	Front and Rear
Sunroof Type	Opening Panoramic		

## Wheels & Tyres


Right Front Tyre Depth	6	Left Front Tyre Depth	6
Right Rear Tyre Depth	7	Left Rear Tyre Depth	7

Cosmetic Damage

6 Schäden



0 Schäden




Component	Damage	Comments
1 Spoiler / Front	Paint / Scratch / Scuff	
2 Fender / Front Left	Paint / Poor Previous Repair	
3 Door / Front Right	Paint / Poor Previous Repair	
4 Door / Back Right	Paint / Poor Previous Repair	
5 Side Panel / Back Right	Paint / Poor Previous Repair	
6 Side Panel / Back Left	Paint / Poor Previous Repair	






1. Spoiler / Front  
Paint / Scratch / Scuff -



2. Fender / Front Left  
Paint / Poor Previous Repair -



3. Door / Front Right  
Paint / Poor Previous Repair -



4. Door / Back Right  
Paint / Poor Previous Repair -



5. Side Panel / Back Right  
Paint / Poor Previous Repair -



6. Side Panel / Back Left  
Paint / Poor Previous Repair -

## Mechanical Condition

### Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

### Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓		

### Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

### Gearbox

Gear Box	✓
----------	---

### Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---



Test Drive Inspection

Steering Wheel			
Steering   Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)