



Mercedes B-Klasse (UKL): 2AKP329

Vinnumber:	W1K2470861J277829	Versionname:	B250e Business Solution 1.3i 218pk/cv 5p 8G-DCT
First Registrationdate:	27/04/2021	Fiscalpower:	
Expertise Mileage:	67219	Power Kw:	118
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	20440.0		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/55/17/98 V				
Winter tyres:	Fr.L.	Semperit: 6 mm	Fr.R.	Semperit: 5 mm
	Re.L.	Semperit: 4 mm	Re.R.	Semperit: 3 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				5.0
Tyre profile depth RL				4.0
Tyre profile depth RR				3.0
Tyre size FL				205/55 R 17 98 V
Tyre size FR				205/55 R 17 98 V
Tyre size RL				205/55 R 17 98 V
Tyre size RR				205/55 R 17 98 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2477
Tyre make FR				2477
Tyre make RL				2477
Tyre make RR				2477

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	1		

Ignition key, Missing, Replace



Door panel RL, Tear, Replace



Headlight L, Broken, Replace



Bumper F, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Tyre RR, Tear, Replace



Step R, Dent(s) and scratch(es), Repair and paint (complete)

