

VIN	W1K247086 1J325868	Brand	MERCEDES	Maintenance date	07/03/2023
Licence Plate	MDR03B	Model	B-KLASSE-BM247-2019	Maintenance mileage	21 639 km
Registration date	28/02/2022	Year	2022	Exterior Color	Other
Odometer	55 678 km	Engine size	-	interior Color	
Fuel	Petrol	Body Type	Minivan	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	8		

Inspection date	14/03/2025	Inspection loc.	Eurotransport Kungsängen		

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Leather	✓
GPS system	✓
Bluetooth	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Central locking	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Led lighting	✓

Refill emergency kit	
Rear parcel shelf	

Charging kit	
Service manual holder	
User manual	
Spare key	
Type 2 charging cables	

DEKRA Automotive Solutions

Tyres

Pirelli 225/45/18 W Summer 6.0 mm		Pirelli 225/45/18 W Summer 6.0 mm	
Pirelli 225/45/18 W Summer 8.0 mm		Michelin 225/45/18 W Summer 8.0 mm	

Winter kit

Continental 205/55/17 T Winter 8.0 mm		Continental 205/55/17 T Winter 8.0 mm	
Continental 205/55/17 T Winter 9.0 mm		Continental 205/55/17 T Winter 9.0 mm	

Damages

1



Part	Charging kit
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum replacement

2



Part	Service
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum

3



Part	Alloy wheel
Position	-
Damages	Scratched
Severity	-
Repair mode	Lumpsum replacement

4



Part	Alloy wheel
Position	-
Damages	Scratched
Severity	-
Repair mode	Lumpsum replacement

5



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Polishing

6



Part	Sill
Position	Right
Damages	Scratched
Severity	-
Repair mode	Lumsum Paintworks

7



Part	Rear parcel shelf
Position	-
Damages	Broken
Severity	-
Repair mode	Lumpsum replacement

8



Part	Door
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumsum Paintworks

9



Part	Armrest hatch
Position	Centre
Damages	Scratched
Severity	-
Repair mode	For info

10



Part	Door
Position	Back left
Damages	Scratched
Severity	-
Repair mode	For info

DEKRA Automotive Solutions

11



Part	Wing
Position	Back left
Damages	Dented
Severity	-
Repair mode	For info

12



Part	Aftermarket wheel
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum replacement

13



Part	Headlight
Position	Back left
Damages	Scratched
Severity	-
Repair mode	For info

14



Part	Bumper moulding
Position	Back
Damages	Broken
Severity	-
Repair mode	Replace

15



Part	Aftermarket wheel
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum replacement

16



Part	Door
Position	Front right
Damages	Dented
Severity	-
Repair mode	For info

17



Part	Aftermarket wheel
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum replacement

18



Part	Headlight
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

19



Part	Bonnet
Position	-
Damages	Stone impact
Severity	-
Repair mode	Lumsum Paintworks

20



Part	Windscreen
Position	-
Damages	Broken
Severity	-
Repair mode	Lumpsum replacement

21



Part	Roof
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info