



MERCEDES A-Klasse Limousine: 2DGM681

Vinnumber:	W1K3G8FB7PJ413804	Versionname:	A-Klasse Limousine A 250 e Business Line (PHEV)
First Registrationdate:	13/03/2023	Fiscalpower:	160kW/218pk 4D/P Auto-7
Expertise Mileage:	45635	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	b511
Fueltype:	Hybrid Petrol		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
GPS storage	HD	Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK


Tyres

205/55/17/95 V				
Summer tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 17 95 V
Tyre size FR				205/55 R 17 95 V
Tyre size RL				205/55 R 17 95 V
Tyre size RR				205/55 R 17 95 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		

Bumper F, Scratch(es), Spot repair




Bonnet, Dent(s), Acceptable




Door seal RL, Deformed / Strained, Replace



Step L, Dent(s) and scratch(es), Spot repair



Wing RL, Dent(s), Spot repair




Door FL, Scratch(es), Spot repair



Wing FL, Scratch(es), Spot repair




Tailgate / Boot, Scratch(es), Polish



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Shutter / cover R, Missing, Replace




Alloy rim FR polished, Scratch(es), Repair and paint (complete)




Wing FR, Scratch(es), Acceptable



Outer door handle FR, Scratch(es), Acceptable



Step R, Dent(s) and scratch(es), Spot repair



Door RR, Dent(s), Acceptable



Door FR, Scratch(es), Acceptable



Wing RR, Scratch(es), Acceptable



Roof, Scratch(es), Repair and paint (complete)

