



Expertise

Protocol number: 41215425
Order No. / Reference: 25082114
Inspection date: 26 Aug 2025

Manufacturer: Mercedes-Benz
VIN: W1K4F8GB3PJ439015

Model: B 250 e 8G-DCT Progressive



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz B 250 e 8G-DCT Progressive	
Vehicle Identification number	W1K4F8GB3PJ439015
Mileage (Read)	68,722 km
First registration	15 Sept 2022
Number of holders	1
Power / Engine displacement	118 kw / 1,332 ccm
Fuel type / Cylinder	Hybr.B/E ext. edition / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Grey Metallic
Doors / Seats	5 / 5
Upholstery type	Part leather
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	86 Tag(e)
Last maintenance on / at	11/2024 at 49,653 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		Letter No.	GM940322
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / ASD 00071		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	Fine dust sticker	
Permitted total weight	2,225 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 95W	Summer tyres on Light alloy	Continental	5mm / 5mm
2)	205/55 R17 95W	Summer tyres on Light alloy	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 91H	Winter tyres on Light alloy	Continental	6mm / 6mm
2)	205/55 R17 91H	Winter tyres on Light alloy	Continental	7mm / 7mm

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel

Equipment

Standard equipment

- ADAPTIVE BRAKE with hill start assist, HOLD function, pre-filling and dry braking in wet conditions
- Airbag: Kneebag for driver
- Airbag: Windowbag
- Anti-lock braking system (ABS)
- Armrest in center console for driver and front passenger, foldable
- Outside temperature display
- Brake assist, active
- Double cup holders at the front
- DYNAMIC SELECT
- Door sills with "Mercedes-Benz" lettering
- Chassis: Comfort chassis
- Velour floor mats
- Speed Limit Assistant
- Rear lights with tail and brake lights in LED light guide technology
- Interior headliner fabric crystal grey
- KEYLESS-GO start function
- THERMATIC automatic climate control
- Headrests in the rear (3)
- Front headrests height adjustable
- 4-way loading eyelets
- Charging cable for household socket, 5m, smooth
- Charging system: Alternating current charging system (AC charging) 3.7 kW
- Steering column mechanically adjustable in height and length
- Mercedes-Benz emergency call system
- Package: Light and Vision Package
- Package: Seat comfort
- Radio: Advanced functions MBUX
- Radio accessories: Digital radio (DAB)
- Remote Services Plus
- Service interval display ASSYST
- Seats: Comfort seats
- Seats: Front seats mechanically adjustable
- Lane Keeping Assist, active
- Bumpers in body color
- Touchpad
- Electronic immobilizer
- Central locking
- Airbag for driver and front passenger
- Airbag: Automatic passenger airbag deactivation
- Airbag: Sidebag for driver and front passenger
- Acoustic environmental protection
- Traction control (ASR)
- ATTENTION ASSIST
- Exterior mirrors left and right heated, electrically adjustable from the inside
- Glasses compartment for driver
- Third brake light in LED technology
- ECO start-stop function
- Electronic Stability Program (ESP)
- 4-way electric window lifter
- Luggage net on driver and passenger backrest
- Transmission: Automatic 8G-DCT
- Rear window wiper with interval control
- Heated rear window with timer control
- ISOFIX child seat attachment with Top Tether in the rear
- Mechanical child safety lock
- Communication module (LTE) for the use of Mercedes me connect services
- Radiator cover with silver painted double louvre and chrome insert
- Load compartment cover (roller blind)
- LED indicators integrated into the exterior mirrors
- Steering wheel: Multifunction sports steering wheel in leather
- Steering: parameter steering
- Gasoline particulate filter
- Package: Non-smoking
- Upholstery: ARTICO man-made leather/Fléron fabric
- Radio: MBUX multimedia system
- Tire pressure monitoring (TPMS)
- Windscreen wipers with rain sensor
- Seat belts B-Class
- Seats: Seat backrests in the rear can be folded down 40:20:40
- socket (12 V)
- Cruise control
- High-visibility vest for drivers
- Heat-insulating glass, green all around
- Decorative elements spiral optics

Extra equipment

- Trailer hitch with ESP trailer stabilization (unlock or lock the ball neck easily and conveniently at the touch of a button.)
- KEYLESS-GO (access and driving authorization system)
- Paint finish: metallic (according to sample card)
- LED High-Performance Headlights (LED High-Performance Headlights offer greater safety at night and a distinctive, striking look. Thanks to LED technology, they illuminate the road better than conventional headlights – while consuming less energy.)



- Package: Business for 250e (hard drive navigation - smartphone integration - traffic sign assistant - preparation for digital key handover - connectivity package navigation - seat heating for driver and front passenger - active parking assistant with PARKTRONIC - public charging package - charging cable for wallbox and public charging stations, 5m, smooth - remote and charging services plus)
- Wheels: 43.2 cm (17") light alloy wheels, 4-spoke design (vanadium silver painted with 205/55 R 17 on 6.5 J x 17 ET 44)
- Package: Parking package with rear view camera (including Active Parking Assistant with PARKTRONIC - rear view camera - ultrasonic sensors)

Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate Part 2 (letter) was available, but the registration certificate Part 1 (certificate) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was verified during the inspection by the undersigned.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and a pit were available for examining the vehicle.
Test drive	No test drive/maneuvering was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - Stone chips - No deduction

The vehicle shows signs of wear commensurate with its age and use.

Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
(*Functional tests of driver assistance systems are not included in the scope of services!*)
- a photo documentation of the vehicle



Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Apparently, no repaired previous damage could be found on the vehicle.

Comments

- Der 2.Radsatz gehört nicht zur Ausstattung und wurde nicht in der Bewertung berücksichtigt.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Additional tyres




Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1K4F8GB3PJ439015

Hersteller / Modell: MERCEDES-BENZ MB B 250 e 8G-DCT Progressive

Datum	KM-Stand	Beschreibung
11.11.2024	49.653	Regelwartungsdienst
19.09.2023	25.330	Regelwartungsdienst