

MERCEDES-BENZ CLA AMG CLA 45 S 4Matic+ AMG Speedshift 8G-DCT



VIN NO W1K5J5EB1PN325463 Registration Number B1PN325463

MOT Date

:::1

Number of Keys

Odometer Reading

2025-08-01

94073 km

Last Service

Last Service Mileage

Number of Owners

2 940/3 km

2025-02-06

_

First Registration Date

Country First Registered

80204

2022-08-05

P2

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250905125200
Inspection Date / Place	2025-09-05 / ARS Altmann AG Riedstadt	Cosmetic Grade	2

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Petrol	Road Worthy	Yes
Colour	Yellow	Engine Size (cc)	1991
Engine Size	2.0	No of Doors	4
Body Type	Coupe	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth/Synthetic Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	With Vendor	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			




































Equipment


Trip Computer	Airbag Status	Anti-lock braking	Cruise control
Digitaldashboard	Remote adjusting wing mirrors	Reversing Camera	Stability control
Electrically adjustable seats	Leather steering wheel	Radio	USB Socket
Alloys wheels	Bluetooth telephone interface	Digital Radio	Front parking sensors
Remote central locking	Satellite navigation	Sunroof	Electrically folding wing mirrors
LED Headlamps	Rear parking sensors		
Equipment Details			

Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	19
Seat Heating	Front	Sunroof Type	Tilt/Slide Glass


Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

Cosmetic Damage




	Component	Damage	Comments
1	Hood	Paint / Stone Chip	
2	Bumper / Front	Paint / Scratch / Scuff	
3	Fender / Front Right	Paint / Stone Chip	



1. Hood Paint / Stone Chip -

2. Bumper / Front Paint / Scratch / Scuff -



3. Fender / Front Right Paint / Stone Chip -

Mechanical Condition

Control Lights			
Display Defect	•	Service Light	•
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light	•
Airbag Warning Light	•	Oil Pressure Warning Light	•
Brake Warning Light	•	Power Steering Warning Light	•
Alternator / Battery	•	No Dashboard Lights	•
Tire Pressure Monitoring System			
Equipments Test			
Other Equipments	•	Central Locking	•
Main & Spare Keys Functioning	•	Electric Windows	•
Navigation System	•	Audio Equipment	•
Parking Sensors / Cameras Functioning	•	AC / Heating System	•
Engine			
Engine Starts	•	Engine Status / EML	•
Engine Leak Visible	•		
Gearbox			
Gear Box	•		
Levels			
Brakes Fluid	⊘	Coolant Fluid	•

Test Drive Inspection

description.

Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss Brake Brake System Anomaly** General **Test Driven Status** No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer Please also note the "UserGuide condition report", which shows the scope of the vehicle

User Guide