



# MERCEDES-BENZ CLA

## CLA 200 7G-DCT

VIN NO W1K5J8HB8SN525990  
Registration Number B8SN525990



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	1	2	18457 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2024-09-23	-

### Inspection Report Summary

Customer	BCA Online	Report Number	P20250922152254
Inspection Date / Place	2025-09-22 / Horst Mosolf GmbH & Co. KG Ketzin	Cosmetic Grade	5

### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Petrol	Road Worthy	No
Colour	Grey	Engine Size (cc)	1332
Engine Size	1.3	No of Doors	4
Body Type	Coupe	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	ARTICO / MICRO CUT schwarz	Seat Covering	Cloth/Synthetic Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

### Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Rental Car	Imported	No
Manufacturer Warrenty			











Equipment

Trip Computer	Airbag Status	Ambientlighting	Anti-lock braking
Bluetooth telephone interface	Digital Radio	Enhanced speaker system	Parking Assistance
Reversing Camera	Split folding rear seats	Central locking	Leather steering wheel
Radio	USB Socket	Alloys wheels	AndroidAuto
AppleCarPlay	Cruise control	Digitaldashboard	Front parking sensors
Remote adjusting wing mirrors	Satellite navigation	Stability control	Electrically folding wing mirrors
LED Headlamps	Rear parking sensors		

Equipment Details


Air Conditioning	Climate Control	Alloy Wheel Size	18
Seat Heating	Front		

Wheels & Tyres

Right Front Tyre Depth	5	Right Rear Tyre Depth	5
------------------------	---	-----------------------	---

Cosmetic Damage

6 Schäden



0 Schäden



Component		Damage	Comments
1	Hood	Bodywork / Breakage	
2	Bumper / Front	Bodywork / Breakage	
3	Corner Bumper / Back Right	Paint / Scratch / Scuff	
4	Tire / Back Left	Tire	
5	Tire / Front Left	Tire	
6	Rim / Front Left	Out of Bodywork / Scratch	





1. Hood  
Bodywork / Breakage -



2. Bumper / Front  
Bodywork / Breakage -



3. Corner Bumper / Back Right  
Paint / Scratch / Scuff -



4. Tire / Back Left  
Tire -



5. Tire / Front Left  
Tire -



6. Rim / Front Left  
Out of Bodywork / Scratch -

## Mechanical Condition

### Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

### Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

### Equipments Test

Central Locking	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

### Gearbox

Gear Box	✓
----------	---

### Levels

Brakes Fluid	✓	Coolant Fluid	⚠
--------------	---	---------------	---



## Test Drive Inspection

Engine			
Engine Noise	✓	Fume Quantity	✓
Power Loss	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Steering Wheel			
Steering   Noise / Anomaly	NA		
Brake			
Brake System Anomaly	✓		
General			
Test Driven Status	NA		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

## Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)