



MERCEDES-BENZ C-Klasse  
C 220 d 9G-TRONIC

VIN NO W1KAF0EB5RR155249  
Registration Number B5RR155249



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	1	2	61051 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2024-01-15	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250922142710
Inspection Date / Place	2025-09-22 / Horst Mosolf GmbH & Co. KG Ketzin	Cosmetic Grade	2

Vehicle Summary



Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Road Worthy	No
Colour	Grey	Engine Size (cc)	1993
Engine Size	2.0	No of Doors	4
Body Type	Sedan	Drive Train	Rear
Seat Colour		No of Seats	5
Seat Covering Name	ARTICO / MICRO CUT schwarz	Seat Covering	Cloth/Synthetic Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Rental Car	Imported	No
Manufacturer Warranty			











Equipment

Trip Computer	Airbag Status	AndroidAuto	AppleCarPlay
Cruise control	Digitaldashboard	Front parking sensors	Remote adjusting wing mirrors
Satellite navigation	Sunroof	Electrically folding wing mirrors	LED Headlamps
Rear parking sensors	USB Socket	Alloys wheels	Anti-lock braking
Bluetooth telephone interface	Digital Radio	Enhanced speaker system	Parking Assistance
Reversing Camera	Stability control	Central locking	Leather steering wheel
Radio			

Equipment Details


Air Conditioning	Climate Control	Alloy Wheel Size	18
Seat Heating	Front	Sunroof Type	Opening Panoramic

Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

7 Schäden



0 Schäden



48 2

Component		Damage	Comments
1	Other	Bodywork / Assembly	
2	Other	Bodywork / Assembly	
3	Corner Bumper / Front Left	Paint / Scratch / Scuff	
4	Corner Bumper / Front Right	Paint / Scratch / Scuff	
5	Fender / Front Right	Bodywork / Dent / Dent	
6	Mirror Shell / Front Right	Bodywork / Breakage	
7	Corner Bumper / Front Left	Paint / Scratch / Scuff	





1.  
Bodywork / Assembly -



2.  
Bodywork / Assembly -



3. Corner Bumper / Front Left  
Paint / Scratch / Scuff -



4. Corner Bumper / Front Right  
Paint / Scratch / Scuff -



5. Fender / Front Right  
Bodywork / Dent / Dent -



6. Mirror Shell / Front Right  
Bodywork / Breakage -





7. Corner Bumper / Front Left  
Paint / Scratch / Scuff -



## Mechanical Condition

### Control Lights

Display Defect	✓	Service Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	ABS Warning Light	✓
Brake Warning Light	⚠	Power Steering Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

### Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

### Equipments Test

Central Locking	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

### Gearbox

Gear Box	✓
----------	---

### Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly ✓

Engine

Engine Noise ✓

The Gears Scratch / Skip / Abnormal Operation ✓

Fume Quantity ✓

Power Loss ✓

Brake

Brake System Anomaly !

General

Test Driven Status NA

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)