



MERCEDES-BENZ C-Klasse  
C 220 d T 9G-TRONIC

VIN NO W1KAH0EB0SF188581  
Registration Number B0SF188581



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	1	2	694 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2024-11-29	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250917135154
Inspection Date / Place	2025-09-17 / Horst Mosolf GmbH & Co. KG Ketzin	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	1993
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Rear
Seat Colour		No of Seats	5
Seat Covering Name	ARTICO / MICRO CUT schwarz	Seat Covering	Cloth/Synthetic Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Rental Car	Imported	No
Manufacturer Warrenty			











## Equipment

Tinted Glass	USB Socket	Alloys wheels	AndroidAuto
AppleCarPlay	Cruise control	Digitaldashboard	Front parking sensors
Remote adjusting wing mirrors	Roof rails	Split folding rear seats	Sunroof
Electrically folding wing mirrors	Leather steering wheel	Radio	Trip Computer
Airbag Status	Ambientlighting	Anti-lock braking	Bluetooth telephone interface
Digital Radio	Enhanced speaker system	Parking Assistance	Reversing Camera
Satellite navigation	Stability control	Central locking	Electrictailgate
LED Headlamps	Rear parking sensors		

## Equipment Details


Air Conditioning	Climate Control	Alloy Wheel Size	18
Seat Heating	Front	Sunroof Type	Opening Panoramic

## Wheels & Tyres

Right Front Tyre Depth	7	Left Front Tyre Depth	7
Right Rear Tyre Depth	7	Left Rear Tyre Depth	7

Cosmetic Damage

3 Schäden



0 Schäden



Component		Damage	Comments
1	Corner Bumper / Front Right	Paint / Scratch / Scuff	
2	Corner Bumper / Front Left	Paint / Scratch / Scuff	
3	Corner Bumper / Front Left	Bodywork / Assembly	





1. Corner Bumper / Front Right  
Paint / Scratch / Scuff -



2. Corner Bumper / Front Left  
Paint / Scratch / Scuff -



3. Corner Bumper / Front Left  
Bodywork / Assembly -

## Mechanical Condition

### Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

### Hybrid/EV

Hybrid System Fault	✓
---------------------	---

### Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

### Equipments Test

Central Locking	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

### Gearbox

Gear Box	✓
----------	---

### Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---



Test Drive Inspection

Steering Wheel			
Steering   Noise / Anomaly		✓	
Clutch			
Clutch Functioning		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓		
Brake			
Brake System Anomaly		✓	
General			

Test Driven Status NA

- ✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage
- ! Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- ⊠ Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)