



MERCEDES-BENZ C-Klasse
C 180 T 9G-TRONIC

VIN NO W1KAH4BB5SF186529
Registration Number B5SF186529



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	1	2	15668 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2024-11-13	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250919152124
Inspection Date / Place	2025-09-19 / Horst Mosolf GmbH & Co. KG Ketzin	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Petrol	Road Worthy	Unknown
Colour	Silver	Engine Size (cc)	1496
Engine Size	1.5	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Rear
Seat Colour		No of Seats	5
Seat Covering Name	ARTICO / MICRO CUT schwarz	Seat Covering	Cloth/Synthetic Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Rental Car	Imported	No
Manufacturer Warranty			







Equipment

Tinted Glass	USB Socket	Alloys wheels	AndroidAuto
AppleCarPlay	Cruise control	Digitaldashboard	Front parking sensors
Remote adjusting wing mirrors	Roof rails	Split folding rear seats	Sunroof
Electrically adjustable seats	Electrictailgate	LED Headlamps	Rear parking sensors
Trip Computer	Airbag Status	Ambientlighting	Anti-lock braking
Bluetooth telephone interface	Digital Radio	Enhanced speaker system	Parking Assistance
Reversing Camera	Satellite navigation	Stability control	Central locking
Electrically folding wing mirrors	Leather steering wheel	Radio	

Equipment Details


Air Conditioning	Climate Control	Alloy Wheel Size	18
Seat Heating	Front	Sunroof Type	Opening Panoramic

Wheels & Tyres

Left Front Tyre Depth	6	Right Rear Tyre Depth	6
Left Rear Tyre Depth	6	Right Front Tyre Depth	6

Cosmetic Damage


4 Schäden



0 Schäden




Component		Damage	Comments
1	Hood	Bodywork / Dent / Dent	
2	Bumper / Front	Bodywork / Breakage	
3	Bumper / Front	Paint / Scratch / Scuff	
4	Bumper / Front	Missing Part	



1. Hood
Bodywork / Dent / Dent -



2. Bumper / Front
Bodywork / Breakage -



3. Bumper / Front
Paint / Scratch / Scuff -



4. Bumper / Front
Missing Part -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Equipments Test

Central Locking	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		NA	
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
= Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)