



# MERCEDES-BENZ E-Klasse

## E 300 de 4Matic T 9G-TRONIC

VIN NO W1KZH1BB5PB099262  
Registration Number B5PB099262



MOT Date

2025-08-01

Last Service

2025-05-15

Number of Owners

1

Last Service Mileage

151308

Number of Keys

2

First Registration Date

2022-08-15

Odometer Reading

163768 km

Country First Registered

Germany

### Inspection Report Summary

Customer	BCA Online	Report Number	P20250829142515
Inspection Date / Place	2025-08-29 / BCA Neuss	Cosmetic Grade	1

### Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Plug - in Hybrid Electric Vehicle Diesel	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1950
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Synthetic Leather
Charging Cables	Type 2	WLTP CO2 Emissions	
Gearbox Type	Automatic		

### Vehicle History & Documents


Service Book Available	Computer Print Out Available	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			













Equipment

Tow ball	Alloys wheels	Anti-lock braking	Cruise control
Digital Radio	Enhanced speaker system	Massage seats	Remote central locking
Roof rails	Seat ventilation	Electrically adjustable seats	Electric tailgate
LED Headlamps	Rear parking sensors	Airbag Status	Ambient lighting
Bluetooth telephone interface	Diesel particulate filter	Digital dashboard	Front parking sensors
Remote adjusting wing mirrors	Reversing Camera	Satellite navigation	Stability control
Electrically folding wing mirrors	Leather steering wheel	Radio	

Equipment Details

Tow Ball Type	Electronic	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	18	Enhanced Speaker System	Burmester
Seat Heating	Front and Rear		


Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5



Cosmetic Damage

5 Schäden



0 Schäden



Component		Damage	Comments
1	Rim / Back Right	Out of Bodywork / Scratch	
2	Mirror Repeater / Right	Glass Break	
3	Windshield / Front	Paint / Chipping	
4	Windshield / Front	Paint / Chipping	
5	Bumper / Front	Paint / Chipping	



1. Rim / Back Right  
Out of Bodywork / Scratch -



2. Mirror Repeater / Right  
Glass Break -



3. Windshield / Front  
Paint / Chipping -



4. Windshield / Front  
Paint / Chipping -



5. Bumper / Front  
Paint / Chipping -



## Mechanical Condition

### Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
All - wheel Drive	✓	No Dashboard Lights	✓
Display Defect	✓	Tire Pressure Monitoring System	✓

### Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

### Gearbox

Gear Box	✓
----------	---

### Equipments Test

AC / Heating System	✓	Main & Spare Keys Functioning	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	!		

### Hybrid/EV

Charge Lead Condition	✓	Charge Port Condition	✓
Hybrid System Fault	✓		

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Brake

Brake System Anomaly

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)