



MERCEDES-BENZ E-Klasse

E 300 de 4Matic T 9G-TRONIC

VIN NO W1KZH1BB5PB099262

Registration Number B5PB099262



MOT Date

2025-08-01

Last Service

2025-05-15

Number of Owners

1

Last Service Mileage

151308

Number of Keys

2

First Registration Date

2022-08-15

Odometer Reading

163768 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250829142515
Inspection Date / Place	2025-08-29 / BCA Neuss	Cosmetic Grade	1

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Plug - in Hybrid Electric Vehicle Diesel	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1950
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Synthetic Leather
Charging Cables	Type 2	WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Computer Print Out Available	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









Equipment

Tow ball	Alloys wheels	Anti-lock braking	Cruise control
Digital Radio	Enhanced speaker system	Massage seats	Remote central locking
Roof rails	Seat ventilation	Electrically adjustable seats	Electric tailgate
LED Headlamps	Rear parking sensors	Airbag Status	Ambient lighting
Bluetooth telephone interface	Diesel particulate filter	Digital dashboard	Front parking sensors
Remote adjusting wing mirrors	Reversing Camera	Satellite navigation	Stability control
Electrically folding wing mirrors	Leather steering wheel	Radio	

Equipment Details


Tow Ball Type	Electronic	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	18	Enhanced Speaker System	Burmester
Seat Heating	Front and Rear		

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

5 Schäden



0 Schäden



Component		Damage	Comments
1	Rim / Back Right	Out of Bodywork / Scratch	
2	Mirror Repeater / Right	Glass Break	
3	Windshield / Front	Paint / Chipping	
4	Windshield / Front	Paint / Chipping	
5	Bumper / Front	Paint / Chipping	



1. Rim / Back Right
Out of Bodywork / Scratch -



2. Mirror Repeater / Right
Glass Break -



3. Windshield / Front
Paint / Chipping -



4. Windshield / Front
Paint / Chipping -



5. Bumper / Front
Paint / Chipping -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Diesel Particulate Filter Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Equipments Test

Main & Spare Keys Functioning	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	!
AC / Heating System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Hybrid/EV

Charge Lead Condition	✓	Charge Port Condition	✓
Hybrid System Fault	✓		

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Brake

Brake System Anomaly

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)