



Mercedes-Benz GLE 350: K467NL

Vinnumber:	W1N1671171A286281	Versionname:	GLE 350dE 2.0 235kW 4Matic automaat (NEDC)
First Registrationdate:	19/01/2021	Fiscalpower:	
Expertise Mileage:	155126	Power Kw:	143
Bodytype:		Body colour	Obsidiaanzwart metallic
Gearbox:	Automatic	Paint type	Metallic
Transmission:	4 Wheel-drive	Type of rims (mounted)	Aluminium
Fueltype:	Hybrid Diesel	Parking lot	325
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Telephone equipment
GPS		Lining leather
Autom climate control		Central consol F
Windows electric F		Luggage cover
Radio multimedia		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors
		Hook

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	275 / 50 / 20 / 113 / W / Aluminium	8,5 mm	Vredestein	Winter
	Right	275 / 50 / 20 / 113 / W / Aluminium	8,1 mm	Vredestein	Winter
Rear	Left	275 / 50 / 20 / 113 / W / Aluminium	7,4 mm	Vredestein	Winter
	Right	275 / 50 / 20 / 113 / W / Aluminium	7,3 mm	Vredestein	Winter

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	1

Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)





Bumper F, Scratch(es), Repair and paint (complete)



Bumper moulding FR, Scratch(es), Replace and paint



Bonnet, Stone chip(s), Repair and paint (complete)



Door RR, Bad repair, Repair and paint (complete)



Mirror side repeater R, Scratch(es), Polish



Charging cable (normal), Missing, Replace



Boot lid covering R, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Roof, Chemical polution, Repair and paint (complete)

