



Mercedes GLB-Klasse (UKL): 2ALX235

Vinnnummer:	W1N2476101W122864	Versionname:	GLB180d Business Solution 2.0d 116pk/cv 5p 8G-DCT
First Registrationdate:	7/05/2021	Fiscalpower:	
Expertise Mileage:	88443	Power Kw:	85
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	Service A +352d		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	215/65/17/99 H			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Firestone: 6 mm	Re.R.	Firestone: 6 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				215/65 R 17 99 H
Tyre size FR				215/65 R 17 99 H
Tyre size RL				215/65 R 17 103 H
Tyre size RR				215/65 R 17 103 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				258
Tyre make RR				258

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Interior, Stain, Acceptable



Windscreen, Stone chip(s), Windscreen repair



Bonnet, Stone chip(s), Acceptable



Bumper F, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Step L, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable





Bumper R, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Fuel cap cover, Scratch(es), Acceptable

