



Mercedes GLB-Klasse (UKL): 2BPM862

Vinnumber:	W1N2476101W160765	Versionname:	GLB180d Business Solution 2.0d 116pk/cv 5p 8G-DCT
First Registrationdate:	4/02/2022	Fiscalpower:	
Expertise Mileage:	193391	Power Kw:	85
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	9282.0		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	215/65/17/99 V			
Summer tyres:	Fr.L.	Goodyear: 7,8 mm	Fr.R.	Goodyear: 8,1 mm
	Re.L.	Pirelli: 6,3 mm	Re.R.	Pirelli: 5,6 mm
Tyre profile depth FL				7.8
Tyre profile depth FR				8.1
Tyre profile depth RL				6.3
Tyre profile depth RR				5.6
Tyre size FL				215/65 R 17 99 V
Tyre size FR				215/65 R 17 99 V
Tyre size RL				215/65 R 17 99 V
Tyre size RR				215/65 R 17 99 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Floor covering FL, Burned, Acceptable



Steering wheel, Worn, Acceptable



Bumper F, Scratch(es), Spot repair



Alloy rim FL polished, Scratch(es), Acceptable



Wing trim FL, Scratch(es), Replace



Door RL, Scratch(es), Repair and paint (complete)



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Internal boot lining R, Worn, Acceptable



Internal boot lining L, Worn, Acceptable



Boot lid covering R, Worn, Acceptable



Door FR, Dent(s), Acceptable



Bodywork, Not original part, Remove lettering



Bodywork, Chemical polution, Check

