

# INSPECTION REPORT


**End Of Contract**

## GENERAL INFO

|                               |                                |
|-------------------------------|--------------------------------|
| File                          | 274795                         |
| License plate                 | 2BBX359                        |
| Vehicle identification number | W1N2476121W158096              |
| Dossier                       | 2021 039 096                   |
| Make                          | Mercedes GLB 200d Business Sol |
| Mileage                       | 90162.00                       |
| First registration            | 24/09/2021                     |
|                               | 21/03/2025                     |

## CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | Y       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | N       |        |
| Towbar (+keys)            |        | Y       |        |
| Certificate of conformity |        | Y       |        |
| Registration certificate  |        | Y       |        |
| Repair kit                |        | Y       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | N       |        |
| Charge back wrong tyres   |        | N       |        |





DAMAGES

| Damages | Type                     | Acceptable |
|---------|--------------------------|------------|
| 318     | Flat Tyre Kit // Replace | Y          |

Damage Pictures



Flat Tyre Kit // Replace-missing