



Mercedes GLC-Klasse (KKL): 2ABV272

Vinnnummer:	W1N2539111F936031	Versionname:	GLC300de Business Solution 2.0d 306pk/cv 5p 4Matic 9G-Tronic
First Registrationdate:	12/02/2021	Fiscalpower:	
Expertise Mileage:	185038	Power Kw:	143
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

235/55/19/105 V				
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				235/55 R 19 105 V
Tyre size FR				235/55 R 19 105 V
Tyre size RL				235/55 R 19 105 V
Tyre size RR				235/55 R 19 105 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				All seasons
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Bumper F, Scratch(es), Acceptable



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Bumper trim R, Scratch(es), Acceptable



Tailgate / Boot, Dent(s), Paintless dent repair



Alloy rim RR polished, Scratch(es), Acceptable



Wing RR, Dent(s), Acceptable



Door FR, Dent(s), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

