



ARVAL
BNP PARIBAS GROUP

2AQW583

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	289524
License plate	2AQW583
Vehicle identification number	W1N2539111V283820
Dossier	2021 160 013
Make	Mercedes GLC 300de 4M
Mileage	59855
First registration	16/05/2021
client availability date	29/07/2025
inspectionDate	30/07/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
41	Windshield // Replace	N
91	Rocker Panel Left // Smart Repair Medium	N
116	Wing Rear Left // Polish	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures




Wing Rear Left // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch




Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch



Rocker Panel Left // Smart Repair Medium-dent



Windshield // Replace-cracked