



MERCEDES GLC: 1YGU660

Vinnumber:	W1N2539131F860437	Versionname:	GLC 200 d Business Solution Limited
First Registrationdate:	27/08/2020	Fiscalpower:	
Expertise Mileage:	143354	Power Kw:	120
Bodytype:		Parking lot	2231
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Body colour	Blue
Fueltype:	Diesel		
Certificate of Conformity	Yes		
Type of rims (mounted)	Aluminium		
Category	Passenger Car		
Registration Certificate Home (BE)	No		
Registration Certificate Car (BE)	Yes		

Options

Radio multimedia		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Front parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	Tow bar collapsible
Cruise Control			
Type of climate control	Autom climate control		
Number of keys total	2		
Type of headlighting	Headlighting LED		
Type of Lining	Lining artificial leather		

Limited Technical Inspection

Tyres

Tyre size RL	235/65 R 17 108 H
Tyre type FL	Winter
Tyre type RL	Winter
Tyre profile depth FR	4.0
Tyre profile depth RR	4.0
Tyre make FR	261
Tyre size FR	235/65 R 17 108 H
Tyre make RR	261
Tyre size RR	235/65 R 17 108 H

235/65/17/108 H			
Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Tyre profile depth FL	4.0
Tyre make FL	261
Tyre size FL	235/65 R 17 108 H
Tyre type FR	Winter
Tyre profile depth RL	4.0
Tyre type RR	Winter
Tyre make RL	261

Assistance equipment

Number of charging cables (normal)	0	Compressor	Yes
Number of charging cables (rapid charge)	0		
Repair kit	Yes		

Total cost ex VAT	424,39
Steering wheel, Worn, Acceptable	0,00



Door panel FL, Broken, Forfeit 166,07



Bumper F, Scratch(es), Spot repair 144,58



Bumper moulding F, Scratch(es), Smart repair 113,74



Bonnet, Stone chip(s), Acceptable 0,00



Door RL, Scratch(es), Acceptable 0,00




Door FL, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Bumper trim R, Scratch(es), Acceptable 0,00



Door RR, Scratch(es), Acceptable 0,00



Door RR, Scratch(es), Acceptable 0,00



Roof, Chemical polution, Acceptable

0,00

