



MERCEDES GLC: 1YKJ828			
Vinnumber:	W1N2539131V262081	Versionname:	GLC 200 d Business Solution
First Registrationdate:	21/09/2020	Fiscalpower:	
Expertise Mileage:	201208	Power Kw:	120
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1127
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options			
Number of keys total:	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Degree of wear

235/55/19/92 H				
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				235/55 R 19 92 H
Tyre size FR				235/55 R 19 92 H
Tyre size RL				235/55 R 19 92 H
Tyre size RR				235/55 R 19 92 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1175,26
-------------------	---------

Bumper F, Scratch(es), Repair and paint (complete)	289,07
--	--------



Windscreen, Stone chip(s), Windscreen repair

0,00



Door RL, Dent(s), Acceptable

0,00



Alloy rim RL polished, Scratch(es), Repair and paint (complete)

199,04



Alloy rim FL polished, Scratch(es), Repair and paint (complete)

199,04



Bumper moulding R, Dent(s), Acceptable

0,00



Tailgate / Boot, Scratch(es), Acceptable

0,00



Rear window, Scratch(es), Polish

0,00



Bumper R, Scratch(es), Repair and paint (complete)

289,07



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

199,04



Wing RR, Dent(s), Acceptable

0,00

