



MERCEDES-BENZ GLC
GLC 200 d 4Matic 9G-TRONIC

VIN NO W1N2539161V309065
Registration Number 161V309065



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2027-01-01	1	2	171141 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2025-02-05	153576	2021-07-14	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250909120408
Inspection Date / Place	2025-09-09 / ARS Altmann AG Riedstadt	Cosmetic Grade	3


Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1950
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	137
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Computer Print Out Available	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tow ball	Trip Computer	Airbag Status	Anti-lock braking
Cruise control	Digital Radio	Front parking sensors	Highbeamassist
Remote adjusting wing mirrors	Reversing Camera	Satellite navigation	Emergencybrakeassist
LED Headlamps	Rain sensitive windscreen wipers	Trafficsignrecognition	USB Socket
Alloys wheels	Bluetooth telephone interface	Diesel particulate filter	Fatiguewarningsystem
Heated wing mirrors	Parking Assistance	Remote central locking	Roof rails
Stability control	Leather steering wheel	Radio	Rear parking sensors

Equipment Details


Tow Ball Type	Electronic	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	17	Seat Heating	Front

Wheels & Tyres

Extra Wheel - 1 Tyre Depth	6	Extra Wheel - 2 Tyre Depth	6
Extra Wheel - 3 Tyre Depth	6	Extra Wheel - 4 Tyre Depth	6

Cosmetic Damage

5 Schäden



0 Schäden



Component		Damage	Comments
1	Bumper / Front	Paint / Scratch / Scuff	
2	Pillar / Back Right	Bodywork / Dent / Dent	
3	Bumper / Back	Paint / Scratch / Scuff	
4	Side Panel / Back Left	Paint / Scratch / Scuff	
5	B Pillar / Center Left	Bodywork / Dent / Dent	



1. Bumper / Front
Paint / Scratch / Scuff -



2. Pillar / Back Right
Bodywork / Dent / Dent -



3. Bumper / Back
Paint / Scratch / Scuff -



4. Side Panel / Back Left
Paint / Scratch / Scuff -



5. B Pillar / Center Left
Bodywork / Dent / Dent -

Mechanical Condition

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
All - wheel Drive	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	✓
Tire Pressure Monitoring System	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Other Equipments	✓	Central Locking	✓
Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Engine			
Fume Quantity	✓	Power Loss	✓
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Brake			
Brake System Anomaly	✓		
Steering Wheel			
Steering Noise / Anomaly	✓		
General			
Test Driven Status	✓		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)