



Mercedes GLC-Klasse (KKL): 2AWU988

Vinnumber:	W1N2539531F979428	Versionname:	GLC300e 2.0i 320pk/cv 5p 4Matic 9G-Tronic
First Registrationdate:	20/08/2021	Fiscalpower:	
Expertise Mileage:	165938	Power Kw:	155
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	ass B6 plus 9200 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	235/60/18/107 H			
Winter tyres:	Fr.L.	Fulda: 6 mm	Fr.R.	Fulda: 6 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				235/60 R 18 107 H
Tyre size FR				235/60 R 18 107 H
Tyre size RL				235/60 R 18 107 V
Tyre size RR				235/60 R 18 107 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2484
Tyre make FR				2484
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	2		
Number of charging cables (rapid charge)	1		

Steering wheel, Worn, Acceptable



Door panel RR, Scratch(es), Acceptable



Bumper F, Scratch(es), Spot repair



Windscreen, Stone chip(s), Replace



Wing FL, Scratch(es), Acceptable




Door FL, Scratch(es), Acceptable



Wing RL, Dent(s) and scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Replace



Interior covering C pillar R, Scratch(es), Replace



Reflector, Broken, Replace



Bumper R, Scratch(es), Acceptable



Wing RR, Dent(s), Acceptable



Door RR, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Acceptable



Wing trim RR, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

