



## Mercedes-Benz GLC 300: K886JL

|                         |                          |                        |                                                            |
|-------------------------|--------------------------|------------------------|------------------------------------------------------------|
| Vinnumber:              | <b>W1N2539531V274858</b> | Versionname:           | <b>GLC 300e 235kW 4M Business Solution Luxury automaat</b> |
| First Registrationdate: | <b>5/01/2021</b>         | Fiscalpower:           |                                                            |
| Expertise Mileage:      | <b>177875</b>            | Power Kw:              | <b>155</b>                                                 |
| Bodytype:               |                          | Body colour            | <b>Obsidiaanzwart Metallic</b>                             |
| Gearbox:                | <b>Automatic</b>         | Paint type             | <b>Metallic</b>                                            |
| Transmission:           | <b>4 Wheel-drive</b>     | Type of rims (mounted) | <b>Aluminium</b>                                           |
| Fueltype:               | <b>Hybrid Petrol</b>     | Parking lot            | <b>770</b>                                                 |
| Number of seats         | <b>5</b>                 |                        |                                                            |
| Type of rims (mounted)  | <b>Aluminium</b>         |                        |                                                            |
| Maintenance needed      | <b>No</b>                |                        |                                                            |

## Options

|                       |          |                            |
|-----------------------|----------|----------------------------|
| Number of keys total  | <b>2</b> | Telephone equipment        |
| Number keys remote    | <b>2</b> | Lining leather             |
| GPS                   |          | Sun Roof electric          |
| Autom climate control |          | Panoramic roof             |
| Windows electric F    |          | Central consol F           |
| Radio multimedia      |          | Luggage cover              |
|                       |          | Headlights Xenon/LED/Laser |
|                       |          | Front parking sensors      |
|                       |          | Rear parking sensors       |
|                       |          | Hook                       |

## Tyres

| Location | Position | Measures                            | Depth  | Make     | Type   |
|----------|----------|-------------------------------------|--------|----------|--------|
| Front    | Left     | 235 / 55 / 19 / 105 / V / Aluminium | 6,0 mm | Goodyear | Summer |
|          | Right    | 235 / 55 / 19 / 105 / V / Aluminium | 5,7 mm | Goodyear | Summer |
| Rear     | Left     | 235 / 55 / 19 / 105 / V / Aluminium | 7,2 mm | Goodyear | Summer |
|          | Right    | 235 / 55 / 19 / 105 / V / Aluminium | 7,2 mm | Goodyear | Summer |

## Assistance equipment

|                                          |          |
|------------------------------------------|----------|
| Number of charging cables (normal)       | <b>1</b> |
| Number of charging cables (rapid charge) | <b>1</b> |

## Door RL, Scratch(es), Polish



## Wing RL, Scratch(es), Repair and paint (complete)



## Bonnet, Stone chip(s), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)

