



MERCEDES Classe G-W463 2018 Benzina  
G AMG 63 585cv auto

VIN NO W1N4632761X364204

Registration Number GC630KN



MOT Date

2024-09-25

Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date

2020-09-28

Odometer Reading

80354 km

Country First Registered

Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250919092234
Inspection Date / Place	2025-09-19 / BCA Lodi	Cosmetic Grade	4

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualified
Fuel Type	Petrol	Gearbox Type	Sequential
Colour	Green	Engine Size (cc)	3982
Engine Size	4.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Leather
Charging Cables		NEDC CO2 Rating (q/km)	330

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			









Equipment

Central locking	Rain sensitive windscreen wipers	LED Headlamps	Digital Radio
Electrically folding wing mirrors	Satellite navigation	Parcel Shef	Remote central locking
Tinted Glass	Traction control	Tyre Mobility Kit	Power assisted steering
Rear parking sensors	Alloys wheels	Electrically adjustable seats	Front parking sensors
Volante multifuncion	Remote adjusting wing mirrors	Cruise control	Tow ball
Trip Computer	Stability control		


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Winter
	HANKOOK HANKOOK-WINTER I*CEPT EVO2 W320A SUV 285/45//R21 - 113V / 3 mm
	HANKOOK HANKOOK-WINTER I*CEPT EVO2 W320A SUV 285/45//R21 - 113V / 3 mm
	HANKOOK HANKOOK-WINTER I*CEPT EVO2 W320A SUV 285/45//R21 - 113V / 3 mm
	HANKOOK HANKOOK-WINTER I*CEPT EVO2 W320A SUV 285/45//R21 - 113V / 3 mm

Cosmetic Damage

19 Danni



2 Danni




Component		Damage	Comments
1	Panel Filling / Front Left	Interior / Broken	
2	Center Console	Interior / Scratched	
3	Tire / Front Left	Tire	
4	Windshield / Front	Glass Break / Impact	
5	Hood	Paint / Chipping	
6	Hood	Bodywork / Poor Previous Repair	
7	Rim / Front Left	Out of Bodywork / Scratch	
8	Door / Front Left	Paint / Scratch / Line	
9	Door / Back Left	Paint / Scratch / Line	
10	Rim / Back Left	Out of Bodywork / Scratch	
11	Fender / Back Left	Bodywork / Dent	
12	Bumper / Back	Paint / Scratch / Line	

13	Fender / Back Right	Paint / Scratch / Line
14	Rim / Back Right	Out of Bodywork / Scratch
15	Door / Back Right	Paint / Scratch / Line
16	Rim / Front Right	Out of Bodywork / Scratch
17	Roof	Bodywork / Dent / Hail Area
18	Bumper / Front	Bodywork / Dent
19	Tire / Front Right	Tire
20	Fender / Front Right	Paint / Scratch / Line
21	Door / Front Left	Paint / Scratch / Line






1. Panel Filling / Front Left  
Interior / Broken -



2. Center Console  
Interior / Scratched -




3. Tire / Front Left  
Tire - Replace



4. Windshield / Front  
Glass Break / Impact -



5. Hood  
Paint / Chipping -




6. Hood  
Bodywork / Poor Previous Repair -






7. Rim / Front Left  
Out of Bodywork / Scratch -



8. Door / Front Left  
Paint / Scratch / Line -



9. Door / Back Left  
Paint / Scratch / Line -



10. Rim / Back Left  
Out of Bodywork / Scratch -



11. Fender / Back Left  
Bodywork / Dent -



12. Bumper / Back  
Paint / Scratch / Line -





13. Fender / Back Right  
Paint / Scratch / Line -



14. Rim / Back Right  
Out of Bodywork / Scratch -



15. Door / Back Right  
Paint / Scratch / Line -



16. Rim / Front Right  
Out of Bodywork / Scratch -



17. Roof  
Bodywork / Dent / Hail Area -



18. Bumper / Front  
Bodywork / Dent -






19. Tire / Front Right  
Tire - Replace



20. Fender / Front Right  
Paint / Scratch / Line -



21. Door / Front Left  
Paint / Scratch / Line -



## Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

## Test Drive Inspection

Other Checks			
Brakes	✓	Steering	✓
Suspension	✓		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		
Equipments Test			
Steering   Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

❗ Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested