



# MERCEDES-BENZ G-Klasse

## G AMG G 63 AMG Speedshift 9G-TRONIC

VIN NO W1N4632761X385913  
Registration Number 761X385913



|              |                      |                         |                          |
|--------------|----------------------|-------------------------|--------------------------|
| MOT Date     | Number of Owners     | Number of Keys          | Odometer Reading         |
| 2026-04-01   | 1                    | 2                       | 85330 km                 |
| Last Service | Last Service Mileage | First Registration Date | Country First Registered |
| -            | -                    | 2021-02-01              | Germany                  |

### Inspection Report Summary

|                         |                                          |                |                 |
|-------------------------|------------------------------------------|----------------|-----------------|
| Customer                | BCA Online                               | Report Number  | P20250815134546 |
| Inspection Date / Place | 2025-08-15 / ARS Altmann<br>AG Riedstadt | Cosmetic Grade | 3               |

### Vehicle Summary

|                    |           |                        |                           |
|--------------------|-----------|------------------------|---------------------------|
| Vehicle Condition  | Runner    | VAT Type               | Qualifying                |
| Fuel Type          | Petrol    | Road Worthy            | Yes                       |
| Colour             | Black     | Engine Size (cc)       | 3982                      |
| Engine Size        | 4.0       | No of Doors            | 5                         |
| Body Type          | SUV       | Drive Train            | All-Wheel-Drive permanent |
| Seat Colour        |           | No of Seats            | 5                         |
| Seat Covering Name |           | Seat Covering          | Synthetic Leather         |
| Charging Cables    |           | NEDC CO2 Rating (q/km) | 330                       |
| Gearbox Type       | Automatic |                        |                           |

### Vehicle History & Documents

|                        |         |                      |    |
|------------------------|---------|----------------------|----|
| Service Book Available | Missing | Next Service Mileage | km |
| Previous Usage         |         | Imported             | No |
| Manufacturer Warrenty  |         |                      |    |







Equipment

|                        |                                  |                                   |                               |
|------------------------|----------------------------------|-----------------------------------|-------------------------------|
| Tinted Glass           | Trip Computer                    | 360°camera                        | Airbag Status                 |
| Ambientlighting        | Bluetooth telephone interface    | Digital Radio                     | Enhanced speaker system       |
| Front parking sensors  | Highbeamassist                   | Remote adjusting wing mirrors     | Satellite navigation          |
| Stability control      | Distancewarningsystem            | Electrically folding wing mirrors | Laneassist                    |
| LED Headlamps          | Rain sensitive windscreen wipers | Trafficsignrecognition            | USB Socket                    |
| Adaptivecruisecontrol  | Alloys wheels                    | Anti-lock braking                 | Cabin Pre Heating             |
| Digitaldashboard       | Fatiguewarningsystem             | Heated wing mirrors               | Massageseats                  |
| Remote central locking | Seatventilation                  | Sunroof                           | Electrically adjustable seats |
| Emergencybrakeassist   | Leather steering wheel           | Radio                             | Rear parking sensors          |

Equipment Details


|                         |                            |                  |       |
|-------------------------|----------------------------|------------------|-------|
| Air Conditioning        | Three Zone Climate Control | Alloy Wheel Size | 22    |
| Enhanced Speaker System | Burmester                  | Seat Heating     | Front |
| Sunroof Type            | Tilt/Slide Glass           |                  |       |

Wheels & Tyres

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Right Front Tyre Depth | 6 | Left Front Tyre Depth | 6 |
| Right Rear Tyre Depth  | 5 | Left Rear Tyre Depth  | 5 |

Cosmetic Damage

5 Schäden



0 Schäden



| Component |                        | Damage                    | Comments |
|-----------|------------------------|---------------------------|----------|
| 1         | Hood                   | Paint / Stone Chip        |          |
| 2         | Rim / Front Right      | Out of Bodywork / Scratch |          |
| 3         | Wheel cover            | Paint / Scratch / Scuff   |          |
| 4         | Side Panel / Back Left | Paint / Scratch / Scuff   |          |
| 5         | Deflector / Front Left | Paint / Stone Chip        |          |




1. Hood  
Paint / Stone Chip -



2. Rim / Front Right  
Out of Bodywork / Scratch -



3. Wheel cover  
Paint / Scratch / Scuff -



4. Side Panel / Back Left  
Paint / Scratch / Scuff -



5. Deflector / Front Left  
Paint / Stone Chip -

## Mechanical Condition

### Engine

|                     |   |                     |   |
|---------------------|---|---------------------|---|
| Engine Starts       | ✓ | Engine Status / EML | ✓ |
| Engine Leak Visible | ✓ |                     |   |

### Equipments Test

|                   |   |                                          |   |
|-------------------|---|------------------------------------------|---|
| Central Locking   | ✓ | Electric Windows                         | ✓ |
| Audio Equipment   | ✓ | AC / Heating System                      | ✓ |
| Other Equipments  | ✓ | Main & Spare Keys<br>Functioning         | ✓ |
| Navigation System | ✓ | Parking Sensors / Cameras<br>Functioning | ✓ |

### Control Lights

|                                    |   |                                                 |   |
|------------------------------------|---|-------------------------------------------------|---|
| ABS Warning Light                  | ✓ | ESP Fault/Traction Control<br>Malfunction Light | ✓ |
| Airbag Warning Light               | ✓ | Oil Pressure Warning Light                      | ✓ |
| Brake Warning Light                | ✓ | Power Steering Warning<br>Light                 | ✓ |
| Alternator / Battery               | ✓ | No Dashboard Lights                             | ✓ |
| Display Defect                     | ✓ | Service Light                                   | ✓ |
| Tire Pressure Monitoring<br>System | ✓ |                                                 |   |

### Gearbox

|          |   |
|----------|---|
| Gear Box | ✓ |
|----------|---|

### Levels

|              |   |               |   |
|--------------|---|---------------|---|
| Brakes Fluid | ✓ | Coolant Fluid | ✓ |
|--------------|---|---------------|---|

Test Drive Inspection

| Steering Wheel                                                                                       |   |                                               |   |
|------------------------------------------------------------------------------------------------------|---|-----------------------------------------------|---|
| Steering   Noise / Anomaly                                                                           |   | ✔                                             |   |
| Engine                                                                                               |   |                                               |   |
| Engine Noise                                                                                         | ✔ | The Gears Scratch / Skip / Abnormal Operation | ✔ |
| Fume Quantity                                                                                        | ✔ | Power Loss                                    | ✔ |
| Brake                                                                                                |   |                                               |   |
| Brake System Anomaly                                                                                 |   | ✔                                             |   |
| General                                                                                              |   |                                               |   |
| Test Driven Status                                                                                   |   | ✔                                             |   |
| ✔ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i> |   |                                               |   |
| ❗ <i>Damages or malfunction detected that requires repairs by the buyer</i>                          |   |                                               |   |
| NA <i>Not applicable</i>                                                                             |   |                                               |   |
| = <i>Not tested</i>                                                                                  |   |                                               |   |

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)