

MERCEDES BENZ EQA 250, 190HK, 2023

Vehicle information

License plate	SKZ26Y	Inspected by	T.H.
Year model	2023	Date of inspection	2025-03-13
Manuf. year/month	2022-06	City	Björkvik
First day in traffic	2022-07	Keys	2
Colour	Mörkgrå	Service book	Elektronisk servicebok
Mileage	60 030 km	Latest service	-
Fuel	EI (EV)	Mileage at the latest service-	
Transmission	Automat	Summer tires	18" alu-fälg 1/1/5/5
Engine effect	140 kW	Winter tires	alu-fälg odubbat 3/3/4/4

Damages

Location	Damage	Comments	Costs excluding VAT
Rims & Tires, Summer	2 tires below 3 mm		270 €
Rims & Tires, Summer	Rim damage 1 wheel		140 €
Bumper, Rear	Cracks large above 100 mm		410 €
Boot lid, Boot lid	Dents 30-100 mm		260 €
Door, Rear right	Scratches above 100 mm		230 €
Bumper, Front	Cracks 30 mm-100 mm		300 €
Bonnet	Chips, several		200 €
Glass, Windshield	Cracks long (Above 150 mm)		640 €
Insteg, Front left	Scratches	Buckla	140 €
Total excl. VAT			2 590 €

Images

[See all images in large format](#)
























Fälgar & Däck Sommar Fälgskada 1 hjul 1 500 kr



Stötfångare Bak Sprickor, stora över 10 cm 4 500 kr



Bagagelucka Bagagelucka Bucklor 3-10 cm 2 900 kr



Dörr Höger bak Repor över 10 cm 2 500 kr



Stötfångare Fram Sprickor, 3-10 cm 3 300 kr







Motorhuv Stenskott flertal 2 200 kr



Glas Vindruta Sprickor långa (Över 15 cm) 7 000 kr



Insteg Vänster fram Repor Buckla 1 500 kr