

Vehicle details

VIN	W1V447603 13979781	Brand	MERCEDES-BENZ	Maintenance date	-
Licence Plate	VP-N6-3G	Model	Vito 114CDI L2 9G-TRONIC RWD Handg. [3200] 4d	Maintenance mileage	-
Registration date	08/06/2022	Year	2022	Exterior Color	Orange Solid
Odometer	75 494 km	Engine size	1950	interior Color	Grey
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	4	Gears	6		

Inspection Details


Inspection date	07/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Tow	✓
Central locking	✓
Electric windows	✓
Independent vehicle heater	✓
Park Distance Control	✓
Audio System	✓


Removable element



Technical Document

User manual	✓
Spare key	✓
Remote key	✓

Tyres



Exterior

2



Part

Other bodywork

Position

-

Damages

Chemical deposit

Severity

-

Repair mode

For info

Buitenkant voertuig

3



Part

Door

Position

Front left

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Repair

4



Part

Bonnet

Position

-

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

Interior damage

1



Part

Fabric seat

Position

Front left

Damages

Stained/dirty

Severity

-

Repair mode

Cleaning