




MERCEDES V-KLASSE: 1YNL827				
Vinnumber:	W1V44781313782556	Versionname:	V 220 d L2 9G-TRONIC	
First Registrationdate:	12/10/2020	Fiscalpower:		
Expertise Mileage:	189347	Power Kw:	120	
Bodytype:		Body colour	Black	
Gearbox:	Automatic	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	2510	
Fueltype:	Diesel			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Light Commercial Vehicle			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Front parking sensors		
Cruise Control		Rear parking sensors		
Steering wheel multifunctional		Type of Tow bar	No Tow bar	
Radio multimedia				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Tyres				
Summer tyres:	245/45/19/102 V			
	Fr.L.	Uniroyal: 1 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 3 mm
Tyre profile depth FL			1.0	
Tyre profile depth FR			3.0	
Tyre profile depth RL			4.0	
Tyre profile depth RR			3.0	
Tyre size FL			245/45 R 19 102 V	
Tyre size FR			245/45 R 19 102 V	
Tyre size RL			245/45 R 19 102 V	
Tyre size RR			245/45 R 19 102 V	
Tyre type FL			Summer	
Tyre type FR			Summer	
Tyre type RL			Summer	
Tyre type RR			Summer	
Tyre make FL			265	
Tyre make FR			265	
Tyre make RL			259	
Tyre make RR			259	
Assistance equipment				
Emergency spare wheel	Yes	Jack	Yes	
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT			765,49	
Interior, Damaged, Acceptable			0,00	




Engine insulation, Damaged, Replace	0,00
-------------------------------------	------




Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------




Alloy rim RL polished, Scratch(es), Repair and paint (complete)	199,04
---	--------



Wing RL, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim FL polished, Scratch(es), Repair and paint (complete)	199,04
---	--------



Tyre FL, Worn, Acceptable	0,00
---------------------------	------



Bumper moulding R, Missing, Acceptable	0,00
--	------



Bumper R, Scratch(es), Acceptable

0,00



Tailgate / Boot, Dent(s), Paintless dent repair

93,06



Tailgate / Boot, Repaired, Acceptable

0,00



Tyre FR, Worn, Acceptable

0,00



Alloy rim RR polished, Scratch(es), Repair and paint (complete)

199,04



Wing RR, Scratch(es), Acceptable

0,00



Door FR, Chemical polution, Polish

0,00



Outside rear-view mirror housing R, Scratch(es), Polish

75,31



Bodywork, Repaired, Acceptable	0,00
--------------------------------	------

