



Mercedes Sprinter (Segm. B3): 1YBH966

Vinnumber:	W1V9072351N088019	Versionname:	Sprinter CDC 314 Functional L3 2.1CDi 143pk/cv 4p RWD
First Registrationdate:	7/07/2020	Fiscalpower:	
Expertise Mileage:	104458	Power Kw:	105
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Type of Tow bar	Tow bar fixed
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	235/65/16/121 R			
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Firestone: 4 mm	Re.R.	Firestone: 4 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				235/65 R 16 121 R
Tyre size FR				235/65 R 16 121 R
Tyre size RL				235/65 R 16 121 R
Tyre size RR				235/65 R 16 121 R
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				256
Tyre make FR				256
Tyre make RL				258
Tyre make RR				258

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Ignition key, Missing, Replace



Dashboard, Hole, Replace



Seat cover FL, Worn, Acceptable



Roof liner, Tear, Check



Engine insulation, Damaged, Replace



Bumper F, Scratch(es), Acceptable



Step L, Scratch(es), Repair and paint (complete)



Tyre FL, Worn, Check



Mirror side repeater L, Crack, Replace



Rear light R, Crack, Replace



Tyre FR, Worn, Check



Central pillar R, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Acceptable



Roof, Scratch(es), Repair and paint (complete)



Bodywork, Damaged, Acceptable

