



Mercedes Sprinter (Segm. B3): 2ADU187

Vinnumber:	W1V9076331P290474	Versionname:	Sprinter 316 L2 2.1CDi 163pk/cv 5p RWD 7G-Tronic+
First Registrationdate:	3/03/2021	Fiscalpower:	
Expertise Mileage:	210020	Power Kw:	120
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	+333dagen		
Battery functioning	Yes		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Light Commercial Vehicle		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	N.A.		

Tyres

	235/65/16/113 R			
Summer tyres:	Fr.L.	Hankook: 7 mm	Fr.R.	Hankook: 7 mm
	Re.L.	Hankook: 7 mm	Re.R.	Hankook: 7 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				235/65 R 16 113 R
Tyre size FR				235/65 R 16 113 R
Tyre size RL				235/65 R 16 113 R
Tyre size RR				235/65 R 16 113 R
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

MOT certificate, Non-conforme, Replace



Seat cover FL, Stain, Cleaning



Ignition key, Missing, Replace



Dashboard, Hole, Smart repair



Bumper F, Scratch(es), Replace



Windscreen, Scratch(es), Replace



Roof pillar L, Dent(s), Acceptable



Bumper trim R, Dent(s) and scratch(es), Acceptable



Boot door panel RL, Dent(s), Acceptable



Bumper R, Dent(s), Acceptable



Boot door panel RR, Dent(s), Acceptable



Wing trim RR, Scratch(es), Replace



Outside rear-view mirror housing R, Scratch(es), Acceptable



Wheel arch cover FR, Deformed / Strained, Acceptable

