



AUDI A7

A7 3.0 TDI quattro S tronic

VIN NO WAUZZZ4G8BN028026
Registration Number G8BN028026



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-05-01	1	2	86289 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2011-05-19	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20251006120600
Inspection Date / Place	2025-10-06 / SULOJA Brackel	Cosmetic Grade	5


Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	2967
Engine Size	3.0	No of Doors	5
Body Type	Coupe	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	4
Seat Covering Name		Seat Covering	Leather
Charging Cables		NEDC CO2 Rating (q/km)	156
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Anti-lock braking	Bluetooth telephone interface	Diesel particulate filter
Heated wing mirrors	Remote central locking	Stability control	Electrically adjustable seats
Electrictailgate	Leather steering wheel	Rear parking sensors	Alloys wheels
Auxiliary Socket	Cruise control	Front parking sensors	Remote adjusting wing mirrors
Satellite navigation	CD Player	Electrically folding wing mirrors	Keyless Entry

Radio

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	18
Seat Heating	Front		

Wheels & Tyres

Right Front Tyre Depth	3	Left Front Tyre Depth	3
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

7 Schäden



0 Schäden



Component	Damage	Comments
1 Side Panel / Back Right	Paint / Poor Previous Repair	
2 Bumper / Front	Paint / Scratch / Scuff	
3 Bumper / Front	Paint / Scratch / Scuff	
4 Side Panel / Back Left	Bodywork / Dent / Dent	
5 Side Panel / Back Left	Bodywork / Breakage / Hole	
6 Bumper / Back	Paint / Scratch / Scuff	
7 Side Panel / Back Right	Paint / Corrosion	



1. Side Panel / Back Right
Paint / Poor Previous Repair -



2. Bumper / Front
Paint / Scratch / Scuff -



3. Bumper / Front
Paint / Scratch / Scuff -



4. Side Panel / Back Left
Bodywork / Dent / Dent -



5. Side Panel / Back Left
Bodywork / Breakage / Hole -



6. Bumper / Back
Paint / Scratch / Scuff -



7. Side Panel / Back Right
Paint / Corrosion -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Display Defect	✓
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Test Drive Inspection

Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly	✓		
Steering Wheel			
Steering Noise / Anomaly	✓		
General			
Test Driven Status	✓		
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
☐ <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)