



AUDI Q7

Q7 50 TDI quattro tiptronic

VIN NO WAUZZZ4M4PD031184
Registration Number M4PD031184



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-07-01	1	2	61491 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2023-07-06	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250912151807
Inspection Date / Place	2025-09-12 / BCA Heidenheim	Cosmetic Grade	1

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	2967
Engine Size	3.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		


Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









Equipment

Tinted Glass	Trip Computer	360°camera	Alloys wheels
AndroidAuto	AppleCarPlay	Cabin Pre Heating	Diesel particulate filter
Digitaldashboard	Front fog lamps	Head up Display	Heated wing mirrors
Remote adjusting wing mirrors	Reversing Camera	Satellite navigation	Split folding rear seats
Sunroof	Electrically adjustable seats	Electrictailgate	LED Headlamps
Rear parking sensors	Tow ball	USB Socket	Airbag Status
Ambientlighting	Anti-lock braking	Bluetooth telephone interface	Cruise control
Digital Radio	Enhanced speaker system	Front parking sensors	Headlamp wash/wipe
Parking Assistance	Remote central locking	Roof rails	Seatventilation
Stability control	Central locking	Electrically folding wing mirrors	Leather steering wheel
Radio	Rear sunblind		

Equipment Details


Tow Ball Type	Electronic	Air Conditioning	Four Zone Climate Control
Alloy Wheel Size	22	Enhanced Speaker System	Bang&Olufsen
Extra Wheel / Tyre Set	Winter Tyres - Alloy	Seat Heating	Front and Rear
Sunroof Type	Opening Panoramic		

Wheels & Tyres

Left Rear Tyre Depth	5	Right Rear Tyre Depth	6
Left Front Tyre Depth	6	Extra Wheel - 1 Tyre Depth	7
Extra Wheel - 2 Tyre Depth	7	Extra Wheel - 3 Tyre Depth	7
Extra Wheel - 4 Tyre Depth	7	Right Front Tyre Depth	6

Cosmetic Damage


3 Schäden



0 Schäden




Component	Damage	Comments
1 Mirror Shell / Front Right	Paint / Scratch / Scuff	
2 Bumper / Front	Paint / Scratch / Scuff	
3 Hood	Paint / Scratch / Scuff	



1. Mirror Shell / Front Right
Paint / Scratch / Scuff -



2. Bumper / Front
Paint / Scratch / Scuff -



3. Hood
Paint / Scratch / Scuff -

Mechanical Condition

Equipments Test

Central Locking	✓	Electric Windows	✓
Navigation System	✓	AC / Heating System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
Other Equipments	✓		

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	All - wheel Drive	✓
Display Defect	✓	Tire Pressure Monitoring System	✓
Service Light	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Coolant Fluid	✓
---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise

The Gears Scratch / Skip / Abnormal Operation

Fume Quantity

Power Loss

Brake

Brake System Anomaly

Gearbox

Automatic Shift

Clutch

Clutch Functioning

General

Test Driven Status

✔

No troubles detected, good condition or correct tests, according to vehicle age and mileage

❗

Damages or malfunction detected that requires repairs by the buyer

NA

Not applicable

⚡

Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

User Guide