



AUDI Q7

Q7 55 TFSI e quattro tiptronic

VIN NO WAUZZZ4M5MD039760
Registration Number M5MD039760



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-07-01	1	2	127158 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2021-08-18	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20251002142447
Inspection Date / Place	2025-10-02 / BCA Neuss	Cosmetic Grade	3



Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Plug - in Hybrid Electric Vehicle Petrol	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	2995
Engine Size	3.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Synthetic Leather
Charging Cables	OUC + Type 2	NEDC CO2 Rating (q/km)	59
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









Equipment

Tinted Glass	360°camera	Alloys wheels	Bluetooth telephone interface
Digital Radio	Front parking sensors	Remote adjusting wing mirrors	Reversing Camera
Satellite navigation	Sunroof	Electrically folding wing mirrors	Leather steering wheel
Radio	Tow ball	Airbag Status	Anti-lock braking
Cruise control	Digitaldashboard	Heated wing mirrors	Remote central locking
Roof rails	Stability control	Electrically adjustable seats	Electrictailgate
LED Headlamps	Rear parking sensors		

Equipment Details


Tow Ball Type	Electronic	Air Conditioning	Three Zone Climate Control
Alloy Wheel Size	21	Seat Heating	Front
Sunroof Type	Opening Panoramic		

Wheels & Tyres


Right Rear Tyre Depth	4	Left Rear Tyre Depth	4
Right Front Tyre Depth	4	Left Front Tyre Depth	4

Cosmetic Damage

4 Schäden




2 Schäden



Component		Damage	Comments
1	Bumper / Back	Paint / Scratch / Scuff	
2	Pillar / Back Right	Paint / Scratch / Scuff	
3	Seat / Back Center	Interior / Worn - out	
4	Seat / Back Center	Interior / Worn - out	
5	Door / Front Right	Paint / Scratch / Scuff	
6	Bumper / Front	Paint / Scratch / Scuff	



1. Bumper / Back
Paint / Scratch / Scuff -



2. Pillar / Back Right
Paint / Scratch / Scuff -



3. Seat / Back Center
Interior / Worn - out -



4. Seat / Back Center
Interior / Worn - out -



5. Door / Front Right
Paint / Scratch / Scuff -



6. Bumper / Front
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓	Display Defect	✓
Service Light	!	Tire Pressure Monitoring System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Electric Windows	✓	Navigation System	✓
AC / Heating System	✓	Main & Spare Keys Functioning	!
Parking Sensors / Cameras Functioning	✓		

Levels

Coolant Fluid	✓
---------------	---

Hybrid/EV

Charge Lead Condition	✓	Charge Port Condition	✓
Hybrid System Fault	✓		

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)